



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

1027  
**RECEIVED**

JUN 03 1991

## INSPECTION REPORT

DIVISION OF  
OIL GAS & MINING

PERMIT NO.: INA/007/021 Inspection Date: May 17, 1991  
 Permittee and/or Operators Name: North American Equities  
 Operator's Representative: \_\_\_\_\_  
 Business Address: \_\_\_\_\_  
 City: \_\_\_\_\_ State: \_\_\_\_\_ Zip: \_\_\_\_\_  
 Mine Name: Blazon #1  
 County: Carbon State: Utah  
 Type of Mining Activity: Underground XX Surface \_\_\_\_\_ Other \_\_\_\_\_  
 Company Official (s): Steve Tanner, rep. Jack Otani (landowner)  
 State Officials (s): Stephen J. Demczak  
 Time of Inspection: 2:10 ( ) a.m. (X) p.m. to 4:30 ( ) a.m. (X) p.m.  
 Partial XX Complete: \_\_\_\_\_ Date of Last Inspection: 4/30/91  
 Weather Conditions: Raining/cold/Partly Snow Covered  
 Acreage: Permitted 320 Disturbed 4.5 Regraded 2.5 Seeded 2.5  
 Bonded 2.5 Enforcement Action: Yes

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	( )	( X )	( )	( X )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( X )	( )	( X )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT COMMENTS  
(continuation sheet)

Page 2 of 2

PERMIT NO. ACT/007/021 INSPECTION DATE May 17, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE:

b. Diversions:

The ditch running north to south direction on the east-side of the property was not in compliance with regulation R614-301-742.100, R614-301-742.300 and R614-301-732.300. NOV 91-39-4-2 violation 1 of 2 was written.

d. Other Sediment Control Measures:

Berms running north to south direction located on pad separating disturbed runoff from entering stream was breached and the silt fences located below former mine portals were not standing. NOV 91-39-4-2 violation 2 of 2 was written.

Copy of report:

Mailed to: Steve Tanner copy to Citizen Complaint File  
Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)  
Filed to: PFO

Inspectors Signature and Number: Stephen J. Demczak #39

Date: 5/24/91

