



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

DRZ
[Signature]

Norman H. Bangertor
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

Partial: XX Complete: Exploration
Inspection Date/Time: August 17, 1993/12:00pm-01:00pm
Date of Last Inspection: June 26, 1993

Mine Name: Blazon #1 County: Carbon Permit Number: ACT/007/021
Permittee and/or Operator's Name: NAE (Insolvent), no known mailing address
Business: Mail cc attn: Steve Tanner, Route #1, Box 146G3, Helper, UT 84526 637-5986
Type of Mining Activity: Underground XX Surface Prep. Plant Other
Officials(s): State: Stephen J. Demczak Federal:
Company Officials: Steve Tanner Weather Conditions: 80's warm
Existing Acreage: Permitted- 0 Disturbed-4.5 Regraded-2.5 Seeded-2.5 Bonded- 0
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ Active/ Inactive/ Temp Cessation/XXBond Forfeiture
Reclamation (Phase I/Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 4 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK; AIR QUALITY PERMIT; BONDING & INSURANCE.

RECEIVED

SEP 02 1993

DIVISION OF OIL, GAS & MINING

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/021 DATE OF INSPECTION: August 17, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

4a. Diversions -

The diversion ditches throughout the property need repair. At the time of the inspection there was no water flowing within the ditches.

4c. Other Sediment Control Measures -

Silt fences are not functioning properly and are need of repair.

RECEIVED

SEP 02 1993

DIVISION OF
OIL, GAS & MINING

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: _____
Mailed to: Bernie Freeman (OSM)
Given to: Joe Helfrich (DOGM)
Filed to: Price Field Office
Date: September 1, 1993

Inspector's Signature and Number: _____

Stephen J. Demczak
Stephen J. Demczak

#39