



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Handwritten initials/signature

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: X Complete: Exploration:
Inspection Date & Time: 7/28/93 10:00am-1:30pm
Date of Last Inspection: 6/29/93

Mine Name: Blazon #1 Mine County: Carbon Permit Number: ACT/007/021
Permittee and/or Operator's Name: NAE(Insolvent), no known mailing address
Business Address: Mail cc attn: Steve Tanner, Route#1, Box 146G3, Helper UT 84526 637-5986
Type of Mining Activity: Underground X Surface Prep. Plant Other
State Officials(s): J. Randall Harden
Company Official(s): None., Steve Tanner, Landowner
Federal Official(s): None.
Weather Conditions: Warm, Clear.
Existing Acreage: Permitted- 0 Disturbed- 4.5 Regraded- 2.5 Seeded- 2.5 Bonded- 0
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ Active/ Inactive/ Temporary Cessation/ X Bond Forfeiture
Reclamation (Phase I/Phase II/Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows list various permit conditions such as PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; CONSTRUCTION/MAINTENANCE/SURFACING; DRAINAGE CONTROLS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK; AIR QUALITY PERMIT; BONDING & INSURANCE.

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/021

DATE OF INSPECTION: July 28, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE

Entrance to the mine site remains posted and blocked by large boulder across the gate to the mine site. No evidence of any activity or use of the site is apparent.

The landowner was contacted and informed of the inspection and declined attending the site inspection. Mr. Tanner did re-affirm his contention that the site should be reclaimed back to the original pre-mining land use and that all features left in conjunction with the alternate land use be eliminated.

4. HYDROLOGIC BALANCE

No runoff or water was found flowing in any of the diversions with the exception of Mud Creek. The flow in Mud Creek has significantly been reduced since the last inspection and was estimated at approximately 0.2 CFS. Silt fences and diversions are in need of repair and maintenance as noted during previous inspections.

8. NONCOAL WASTE

Power poles, glass and other hardware from the power lines and street lamps which were vandalized on the site remain. Portions of these materials are found lying in and adjacent to Mud Creek.

9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES

Cutthroat trout seen during the previous inspection were not evident. Reduced flow in the stream channel has also reduced fish habitat. It was also assumed that spawning in Mud Creek had ended.

Note - This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Marcia Petta (OSM) Steve Tanner (Landowner)

Given to: Daron Haddock & Joe Helfrich (DOGM)

Inspector's Signature:



13 Date: 8/31/93