

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/021

DATE OF INSPECTION: 11/4/94

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS -

The identification signs at the main gate can be seen from the public road. Information is outdated due to the company insolvency.

4a. DIVERSIONS -

The diversions were snow covered and sediment filled. No changes have taken place since last inspection with regards to diversions.


4b. SEDIMENT PONDS -

The sediment pond was snow covered with no signs of hazardous conditions existing. The pond was not discharging and would appear not to in the near future.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: _____ Bernie Freeman (OSM)
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office
Date: November 21, 1994

Inspector's Signature:  #39
Stephen J. Demczak