



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

## INSPECTION REPORT

Norman H. Bangarter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

Partial: XX Complete:      Exploration     

Inspection Date/Time: April 19, 1994/09:00am-10:00am

Date of Last Inspection: March 17, 1994

Mine Name: Blazon #1 County: Carbon Permit Number: ACT/007/021  
Permittee and/or Operator's Name: NAE (Insolvent), no known mailing address  
Business: Mail cc attn: Steve Tanner, Route #1, Box 14663, Helper, UT 84526 637-5986  
Type of Mining Activity: Underground XX Surface      Prep. Plant      Other       
Officials(s): State: Stephen J. Demczak Company:       
Federal Officials:      Weather Conditions: Warm 50's, 12" Wet Snow  
Existing Acreage: Permitted- 0 Disturbed- 4.5 Regraded- 2.5 Seeded- 2.5 Bonded- 0  
Increased/Decreased: Permitted-      Disturbed-      Regraded-      Seeded-      Bonded-       
Status: Exploration/ Active/ Inactive/ Temp Cessation/XX Bond Forfeiture  
Reclamation ( Phase I/ Phase II/ Final Bond Release/ Liability      Year)

### REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

#### Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[XX]	[ ]	[XX]	[ ]
2. SIGNS AND MARKERS	[ ]	[ ]	[ ]	[ ]
3. TOPSOIL	[ ]	[ ]	[ ]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[ ]	[ ]	[ ]	[ ]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
c. OTHER SEDIMENT CONTROL MEASURES	[ ]	[ ]	[ ]	[ ]
d. WATER MONITORING	[ ]	[ ]	[ ]	[ ]
e. EFFLUENT LIMITATIONS	[ ]	[ ]	[ ]	[ ]
5. EXPLOSIVES	[ ]	[ ]	[ ]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	[ ]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
8. NONCOAL WASTE	[ ]	[ ]	[ ]	[ ]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[ ]	[ ]	[ ]	[ ]
10. SLIDES AND OTHER DAMAGE	[ ]	[ ]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[ ]	[ ]	[ ]	[ ]
12. BACKFILLING AND GRADING	[ ]	[ ]	[ ]	[ ]
13. REVEGETATION	[ ]	[ ]	[ ]	[ ]
14. SUBSIDENCE CONTROL	[ ]	[ ]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[ ]	[ ]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[ ]	[ ]	[ ]	[ ]
b. DRAINAGE CONTROLS	[ ]	[ ]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[ ]	[ ]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[ ]	[ ]	[ ]	[ ]
19. AVS CHECK (4th Quarter-April, May, June) _____ date	[ ]	[ ]	[ ]	[ ]
20. AIR QUALITY PERMIT	[ ]	[ ]	[ ]	[ ]
21. BONDING & INSURANCE	[ ]	[ ]	[ ]	[ ]

INSPECTION REPORT  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/021 DATE OF INSPECTION: April 19, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

NOTE: The site was inaccessible. Therefore, only paperwork was reviewed.

1. Permit -

- a) No additional information dealing with Blazon has been reported into the files recently.
- b) The North American Equities as an entity that no longer exists. There is no agent for service for notice or regulatory action.
- c) The preliminary estimate of the monies required to reclaim the site for use of wildlife and grazing may exceed \$100,000. The forfeiture of the reclamation bond is for the amount of \$38,000.
- d) The Division, in the near future, will be designing a reclamation plan for Blazon. There is a possibility that the site will be reclaimed in 1994.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: \_\_\_\_\_  
Mailed to: Bernie Freeman (OSM)  
Given to: Joe Helfrich (DOGM)  
Filed to: Price Field Office  
Date: May 10, 1994

Inspector's Signature and Number: Stephen J. Demczak #39  
Stephen J. Demczak