

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/021

DATE OF INSPECTION: 4/26/95

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT -


The Blazon permit has been revoked by the Division and DOGM is in charge of final reclamation of this coal mine. Plans and designs for reclamation are at Division headquarters but no permit actions have taken place since the revocation. No monitoring requirements by permittee have been done under DOGM control. Monthly inspections are done when the site is accessible. The Division makes monthly attempts to inspect this site.

NOTE: The site was inaccessible due to high amount of snow on the road to the site. No tire tracks to the mine site.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: _____
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office
Date: May 15, 1995

Inspector's Signature:  #39
Stephen J. Demczak