



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: XXX Complete: Exploration:
Inspection Date & Time: 8/27/96 / 7:00a.m.-11:00a.m.
Date of Last Inspection: 7/25/96

Mine Name: Blazon Mine #1 County: Carbon Permit Number: ACT/007/021
Permittee and/or Operator's Name: NAE (Insolvent), No Known Mailing Address
Business Address: cc: Steve Tanner, Rt#1 Box 146G3, Helper, Utah 84526 (637-5986)
Type of Mining Activity: Underground XXX Surface Prep. Plant Other
Company Official(s): Steve Tanner
State Officials(s): Stephen J. Demczak Federal Official(s): None
Weather Conditions: Warm, 70's
Existing Acreage: Permitted-0 Disturbed-4.5 Regraded-2.5 Seeded-2.5 Bonded-0
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ Active/ Inactive/ Temporary Cessation/ XXX Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Contains 21 rows of inspection items with checkboxes for evaluation status.



INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/021

DATE OF INSPECTION: 8/27/96

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT -

This month the Division placed a notification on the gate to Blazon which stated the Division has permission to reclaim the site. This appears to be granted by the Board of Oil, Gas and Mining. The letter also states that the Division will reclaim the pond, remove culverts, cap water well, and regrade the area. This letter was signed by the Director of Oil, Gas and Mining.

4A. DIVERSIONS -

The diversions have not changed since the last inspection. The Division is in the process of contracting the cleaning out of the ditches, reconstructing a berm, and capping of the well.

4B. SEDIMENT POND -

The sediment pond was inspected and it appears to have no hazardous conditions. Pond was not discharging during the inspection.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Steve Tanner Marcia Petta (OSM)
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office
Date: August 30, 1996

Inspector's Signature:  #39
Stephen J. Demczak