

0003

December 21, 1982

Inspection Memo
to Coal File

#7

RE: C.V. Spur
Beaver Creek Coal Company
ACT/007/022
Carbon County, Utah

A very quick partial inspection was conducted by Sandy Pruitt, Division of Oil, Gas and Mining, Dave Meyer and Scott Raymond, Beaver Creek Coal Company, on November 23, 1982, to check on the excess water problem at C.V. Spur's sediment ponds #1, #2, #3 and #6. The thickener overflow pond was down. Ponds #1, #2, #3 and #6 were all full. There had been no additional work done on sediment ponds #4 and #5.

SANDY PRUITT 
FIELD SPECIALIST

SP/tck

cc: Tom Ehmett, OSM

Statistics:

See C & W Mine memo dated, November 29, 1982