

0008

November 16, 1982

Inspection Memo
to Coal File

#7
RE: Beaver Creek Coal Company
C.V. Spur
ACT/007/022
Carbon County, Utah

DATE: June 16-17, 1982
TIME: 3:15 p.m. - 4:45 p.m.; 8:15 a.m. - 12:15 p.m.
WEATHER: Fair
COMPANY OFFICIAL: Dave Meyer
STATE OFFICIAL: Sandy Pruitt
ENFORCEMENT ACTION: None

Compliance with Permanent Performance Standards

UMC 771 et al Permits

An interim approval letter dated September 24, 1981, was available on site as required. C.V. Spur has 157 shares allocated for industrial water use. This may be increased to 200 shares in the future. In addition, a .25 cfs direct diversion is available for the plant from November to March. The plant used 88.65 acres feet of water in 1979.

UMC 817.41 - .57 Hydrologic Balance

A broken irrigation water line is draining onto the C.V. Spur site, the water ponds at the base of the coarse refuse pile. It was explained that the system would be replaced with a cement ditch in the fall. Additional water on site is in excess of the sediment pond runoff capacity.

Ponding near the plant refuse bin can be alleviated with ditch and sump maintenance.

UMC 817.52 Hydrologic Balance Monitoring

Water monitoring data for the first quarter January to March 1982 was available for inspection. No compliance problems were evident.

SANDY PRUITT
FIELD SPECIALIST

SP/tck

cc: Tom Ehmett, OSM

Statistics:

See Gordon Creek #2 memo dated, June 22, 1982