

0014

May 5, 1982

Inspection Memo
to Coal File:

RE: Castle Valley Spur
Beaver Creek Coal Company
ACT/007/02~~8~~2
Carbon County, Utah

A partial inspection of the above-mentioned operation was conducted by Sandy Pruitt of the Division and Dave Meyer of Beaver Creek Coal Company on April 27, 1982. The surface operation was mostly in compliance with performance standards. Topsoil protection in abatement to NOV #1 (N82-1-2-2) was not yet completed. Drainage inlets to pond #4 should be riprapped to minimize erosion in accordance with UMC 817.45 and 817.46. During the inspection, it was evident that both the inspector and Dave Meyer needed to find out more about the drainage system from the prep plant and drainage control in areas surrounding the refuse piles to determine mine plan design adequacy in regard to ditch maintenance and ponding problems on-site.

SANDY PRUITT
RECLAMATION OFFICER

cc: Tom Ehmett, OSM
Dave Meyer, Beaver Creek Coal Company
Inspection Staff

SP/btd

Statistics:

See Plateau Mine memo dated May 5, 1982
Grant: A & E