

0006

Beaver Creek Coal Company  
P.O. Box AU  
Price, Utah 84501  
Telephone 801 637-5050

File ACT/007/022  
Folder No. 2



Copy to Ev,  
Dave D., Lynn  
John Parr  
JIM

November 10, 1983

NOV 10 1983

Mr. James W. Smith, Jr.  
Coordinator of Mined Land Development  
Utah Division of Oil, Gas & Mining  
4241 State Office Bldg.  
Salt Lake City, Utah 84114

RECEIVED  
NOV - 10 1983

RE: D.O.C./T.D.  
C.V. Spur Prep Plant  
ACT/007/022

DIVISION OF  
OIL, GAS & MINING

Dear Mr. Smith:

Enclosed are 8 copies each of Beaver Creek Coal Co.'s response to the deficiencies noted in your letter of 11/3/83.

The following will serve as a checklist for each of the response locations for the deficiencies listed in your letter:

UMC 783.19 Vegetation Information

1. See revised Plate 9-1, p. 9-11a, and p. 9-14.
2. Shrub density from the affected area is being collected at this time by a consultant. Due to the very short notice on this deficiency, this data will be submitted under separate cover no later than 11/17/83.

UMC 784.13 Reclamation Plan: General Requirements

- (b) The comments under this section were addressed in the D.O.C. response of 10/6/83.

Bond estimate change on revised page 3-69.

(Last paragraph) The Price River Seed Mix has been revised on Table 3-3 and page 3-58.

UMC 784.14 Reclamation Plan and Protection of Hydrologic  
Balance


1. Clarified on page 7-56.
2. French drain shown on revised Plate 3-7.
3. Clarified on page 7-56.

UMC 784.16 Reclamation Plan: Ponds, Impoundments, Banks,  
Dams and Embankments

1. Requested items are submitted as additional Plates  
3-6a and 3-6b.

It is our hope this information will be adequate to allow the  
Division to make a final determination of completeness and  
proceed with the T/A on this plan. If you have any question or  
need any further information, please let me know.

Respectfully,



Dan W. Guy  
Manager of Permitting  
and Compliance

cc: R.D. Robison  
S.R. Raymond  
File

DG/cn