

February 8, 1983

#7

Inspection Memo  
to Coal File:RE: C. V. Spur  
Beaver Creek Coal Company  
ACT/007/022  
Carbon County, Utah

A partial inspection of the C. V. Spur site was conducted on January 18, 1983 by Sandy Pruitt and Scott Raymond. Conditions on-site had not changed much since the January 10, 1983 inspection but a three to four foot tall berm had been constructed as required to prevent drainage onto a small area requested for exemption from sediment control. No erosion or off-site drainage was detected due to the poor maintenance of drainage ditches and culverts throughout the operation but it was requested that maintenance of these structures be maintained as soon as the ground thaws or a violation of UMC 817.45 will be issued.

SANDY PRUITT <sup>SP</sup>  
FIELD SPECIALIST

SP/lm

cc: Tom Ehmett, OSM  
Joe Helfrich, DOGM  
Scott Raymond, BCCC

Statistics:

See Gordon Creek Mine memo, dated February 8, 1983.