

0015

File

December 27, 1984

TO: Coal File, Inspection and Enforcement File
FROM: Ken Wyatt, Mining Field Specialist *YW*
RE: Beaver Creek Coal Company, C. V. Spur Preparation Plant, ACT/007/022, #7, Carbon County, Utah

On December 20, 1984, a partial inspection of the above referenced mine facility was conducted by Ken Wyatt and Tom Wright, Mining Field Specialists for the Division. Dan Guy of Beaver Creek Coal Company accompanied these inspectors into the field. The weather was cold with heavy snow falling with eight inches on the ground. Visibility was less than a quarter mile.

Straw bales have been installed into the ditch along the east side of the subsoil stockpile. Five bales were placed in a series to contain runoff from the Jensen trucking facility. When this area (Jensen facility) is deleted from the permit area, the culvert under the railroad tracks will be blocked off. Mr. Guy indicated that a small catch basin would be constructed to treat runoff from the trucking area although this area would not fall under current coal regulations.

No compliance problems were encountered.

btb

cc: Donna Griffin
Dan Guy
Joe Helfrich

Statistics:

See Huntington Canyon #4 Mine memo dated December 24, 1984.
0379R-23