

September 9, 1985

TO: Coal File, Inspection and Enforcement Folder  
FROM: Tom Wright, Mining Field Specialist TW  
RE: Beaver Creek Coal Company Preparation Plant, ACT/007/022,  
Carbon County, Utah

On September 5, 1985, I conducted a partial inspection of the C. V. Spur Preparation Plant. No one was available so I conducted the inspection alone. After completing the inspection I contacted Burk Biersdorf, Plant Supervisor.

All sediment ponds for the site contained water during this inspection. Pond #6 contained water in the two upper cells but no evidence of any discharge from the pond was noted.

Beaver Creek intends to reconstruct Ponds #6 and #4 this fall. Stakes outlining the reconstruction have been posted around the ponds. No work on this reconstruction had been started by this date.

Topsoil stockpiles for the area remain stable with no evidence of significant loss or erosion of material. Vegetation on the two storage areas continues to suffer with little development. It appears that the cover on these stockpiles corresponds to cover on surrounding undisturbed areas.

No violations were noted on this inspection.

re

cc: Donna Griffin  
Joe Helfrich  
Ken May  
John Whitehead  
Dan Guy

Statistics:

Vehicle: EX 49611, 542 miles  
Per Diem: 1 person X 1 day 10 hours = \$56.07  
Grant: A&E  
0342Q-5