

File

May 20, 1985

TO: Coal File, Inspection and Enforcement Folder
FROM: Tom Wright, Mining Field Specialist ^{TW}
RE: Beaver Creek Coal Company, C. V. Spur Preparation Plant,
ACT/007/022, Folder #7, Carbon County, Utah

A partial inspection of the C. V. Spur Preparation Plant was conducted on May 9, 1985. Neither Dan Guy who handles compliance for Beaver Creek or Buck Biersdorf, Plant Superintendent were available so I conducted the inspection alone. The weather was sunny and warm.

No additional cleaning of sediment from the ditch for routing discharge from the #4 Sediment Pond outlet to the #6 Sediment Pond had been done since the last inspection. This ditch had been cleared previously, from the #4 Pond outlet to the first road crossing over the ditchline. Culverts for the ditchline were clear and functional with no evidence of recent flow.

No discharge was occurring from any sediment pond during this inspection and it appeared that none had occurred since the last inspection.

Vegetation was improving on the slopes of the topsoil stockpiles although most of the cover is still in clumps. No significant erosion or loss from these stockpiles was noted.

The area disturbed on the northern side of the permit area for installation of a waterline has stabilized and volunteer vegetation on this site is increasing over the area. Both ditches on the area for control of runoff appeared functional.

No violations were noted on this inspection.

re

cc: Donna Griffin, OSM
Dan Guy, BCCC
Joe Helfrich, DOGM
John Whitehead, DOGM

Statistics: See Blazon memo dated May 20, 1985

0244Q-13