



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 12/22/86, 1:00PM

Permittee and/or Operators Name: BEAVER CREEK COAL COMPANY
 Business Address: P.O. Box 1378 PRICE, UTAH 84501
 Mine Name: C.V. Spur Permit Number: Act/007/022
 Type of Mining Activity: Underground Surface Other Prep.P.+Loadout
 County: Carbon
 Company Official (s): Dan Guy
 State Official(s): Phil Ralphs & Tom Munson
 Partial: X Complete: Date of Last Inspection: 11/19/86
 Weather Conditions: Partly Cloudy
 Acreage: Permitted 160 Disturbed 110 Regraded Seeded Bonded 110
 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/022

DATE OF INSPECTION 12/22/86

(Comments are Numbered to Correspond with Topics Listed Above)

4c.) SEDIMENT PONDS AND IMPOUNDMENTS

All the sediment ponds and related facilities were inspected and determined to be in good operational condition. Ponds #2 and 3 which were observed to have reached their 10 year- 24 hour storm water capacity on the last inspection had been pumped dry and this water was sent to the preparation plant to be used for dust suppression and makeup water in the plant. No discharge of this water occurred and therefore no water samples were taken. No further problems or concerns were noted at this inspection.

Copy of this Report:

Mailed to: CC: Dan Guy(BCCC)& Donna Griffith(OSM)

Given to: John Whitehead, Tom Munson, Joe Helfrich

Inspectors Signature and Number:

Tom Munson Date: 1/14/87