



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

0012

Norman H. Bangert, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

get on

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: January 12, 1989
7:30am to 12:00pm

Permittee and/or Operators Name: Beaver Creek Coal Co.
Business Address: P.O. Box 1378 Price, Utah 84501
Mine Name: C.V. Spur Permit Number: ACT/007/022
Type of Mining Activity: Underground Surface Other XX (LOADOUT)
County: Carbon State: Utah
Company Official(s): Dan Guy
State Official(s): Bill Warnack
Partial: Complete: XX Date of Last Inspection: December 6, 1988
Weather Conditions: Clear and cold
Acreage: Permitted 160 Disturbed 108 Regraded Seeded Bonded 160
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	(X)	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	(X)
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	(X)	()	()	()
7. COAL PROCESSING WASTE	(X)	()	()	(X)
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	()
12. BACKFILLING AND GRADING	()	()	(X)	()
13. REVEGETATION	(X)	()	()	()
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	(X)	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	(X)	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/022

DATE OF INSPECTION January 12, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

Approximately 4-6 inches of snow covered the site. The inspection commenced with a review of the pertinent mine records, permits, and correspondences. At the present time, there are no outstanding violations or permit stipulations. Mr. Dan Guy (BCCC) accompanied the undersigned during all phases of the inspection.

1. PERMITS:

The associated mine documents were reviewed and found in good order. As of this writing, there has not been any amendments or modifications to the present approved plan. However, items addressed in previous complete inspections are listed for reference purposes only.

1. Permit approved 8/6/84 and expires 8/5/89; mid-term approved 4/2/87.
2. Bond has been posted in the amount of \$2,017,669 with Federal Insurance Company for 160 acres.
3. Liability insurance through the Insurance Company of North America effective 1/1/88 for life operation.
4. Revised water monitoring plan approved by the Division on 3/2/88.
5. Approval granted by the Division to suspend annual raptor surveys and reports on 7/19/88.
6. Amendment addressing sediment pond cleanout levels approved on 1/22/88 by the Division.
7. Notice of intent to modify the UPDES permit sent by BCCC on 1/8/87.
8. Vegetation test plot deficiencies addressed and hand delivered to John Whitehead (DOGM) on 1/4/89.

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

Pond inspections were complete through the 4th quarter of 1988. Sediment levels for all ponds were well below the maximum storage capacity.

INSPECTION REPORT
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/007/022

DATE OF INSPECTION January 12, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

4e. SURFACE AND GROUNDWATER MONITORING:

Water monitoring results were reviewed and found in good order. Stations were monitored according to the approved plan. Samples were collected in May and November; final data was being compiled at this time since lab results were not received until 12/27/88.

7. COAL PROCESSING WASTE:

Coal processing waste inspections were made through the 4th quarter of 1988; no associated erosion or instability problems were noted.

NOTE: Although the property was covered with snow, drainage controls (ditches, culverts, etc.) were still operable and functional. However, there was not any runoff observed during the inspection.

Copy of this Report:

Mailed to: Dan Guy, BCCC

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM

Filed to: PFO

Inspectors Signature and Number: William A. Warmack #30 Date: Jan. 17, 1989

William A. Warmack 1/17/89