



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

pgl
gch

INSPECTION REPORT

INSPECTION DATE & TIME: March 5, 1990
10:00 a.m.-11:15 a.m.

Permittee and/or Operators Name: Beaver Creek Coal Company (BCCC)
Business Address: P.O. Box 1378 Price, UT 84501
Mine Name: C. V. Spur Permit Number: ACT/007/022
Type of Mining Activity: Underground Surface X Other
County: Carbon
Company Official (s): Clay Cloward
State Official(s): Susan White, Henry Sauer
Partial XX Complete: Date of Last Inspection: February 23, 1990
Weather Conditions: Cool, Sleet and Rain
Acreage: Permitted 160 Disturbed 108 Regraded Seeded Bonded 108
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	(X)
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/022

DATE OF INSPECTION March 5, 1990

(Comments are Numbered to Correspond with Topics Listed Above)


1. PERMITS
2. SIGNS AND MARKERS
3. TOPSOIL
4. HYDROLOGIC BALANCE
 - a. STREAM CHANNEL DIVERSIONS
 - b. DIVERSIONS
 - c. SEDIMENT PONDS AND IMPOUNDMENTS
 - d. OTHER SEDIMENT CONTROL MEASURES
 - e. SURFACE AND GROUNDWATER MONITORING
 - f. EFFLUENT LIMITATIONS
5. EXPLOSIVES
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL
- d. COAL PROCESSING WASTE
8. NONCOAL WASTE
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES
10. SLIDES AND OTHER DAMAGE
11. CONTEMPORANEOUS RECLAMATION
12. BACKFILLING AND GRADING
13. REVEGETATION
14. SUBSIDENCE CONTROL
15. CESSATION OF OPERATIONS
16. ROADS
 - a. CONSTRUCTION
 - b. DRAINAGE CONTROLS
 - c. SURFACING
 - d. MAINTENANCE
17. OTHER TRANSPORTATION FACILITIES
18. SUPPORT FACILITIES UTILITY INSTALLATIONS

: Copy of this Report:

Mailed to: John Kathman-OSM and Dan Guy (BCCC)

Given to: Joe Helfrich-DOGM

Inspectors Signature and Number: #32



Date: 3/15/90

INSPECTION REPORT
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/007/022

DATE OF INSPECTION March 5, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments

Clay Cloward (Beaver Creek Coal Company) accompanied Susan White (DOGM) and the undersigned inspector on this partial state inspection. Weather conditions were cool and snowing.

4. Hydrologic Balance:

4(b) Diversions

The following ditches require minor grading to facilitate drainage: the diversion ditch southeast of the wash plant and the diversion ditch east of the Jenson Truck Dump.

4(c) Sediment Ponds and Impoundments

Sediment Pond #2 has been cleaned out. Sediment pond waste has been placed on the coal processing waste bank.

16. Roads:

16(b) Drainage Controls

The road diversion ditch on the east side of the Trail Mountain Truck Dump needs to be reestablished.

djh
AT43/32-34