



gd page

inspection report

Permit No. ACT/007/022

Inspection Date 18 July 1991

Permittee/Operator Name Mountain Coal Company

Business Address P.O. Box 1378

City Price State Utah Zip 84501

Mine C.V. Spur Loadout Surface Underground Other

County Carbon State Utah

Company Official(s) Bill Biersdorff

State Official(s) Jess Kelley

Time of inspection 7:30 a.m. p.m. to 11:00 a.m. p.m. Partial Complete

Date of last inspection 3 June 1991 Weather conditions Warm and cloudy

Acreage 160 Permitted 108 Disturbed Regraded Seeded 108 Bonded

Enforcement Action None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS		YES	NO	N/A	COMMENTS
1. Permits	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	9. Protection of fish, wildlife, and related environmental values	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	10. Slides and other damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	11. Contemporaneous reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Hydrologic balance					12. Backfilling and grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
a Stream channel diversions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
b Diversions	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	14. Subsidence control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
c Sediment ponds and impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	15. Cessation of operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
d Other sediment control measures	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	16. Roads				
e Surface and groundwater monitoring	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Construction	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
f Effluent limitations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Drainage controls	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Surfacing	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Development waste and spoil disposal	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	- Maintenance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal processing waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	17. Other transportation facilities	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal waste	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	18. Support facilities and utility installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

INSPECTION REPORT COMMENTS

Permit No. ACT/007/022

Inspection Date 18 July 1991

Please number comments to correspond with topics on previous page.

2. SIGNS & MARKERS

The company is currently changing its name from Beaver Creek Coal Company to Mountain Coal Company. New signs have been ordered but have not yet arrived.

3. TOPSOIL

Topsoil stockpiles are in good condition but have a very sparse covering of vegetation, despite recent rain.

4. HYDROLOGIC BALANCE

(c) Sediment Ponds and Impoundments--Sediment ponds are in good condition and contain some water. Pond banks are free from rills and gullies and inlets are in good repair. Ponds are not discharging.

5. COAL PROCESSING WASTE

Contour furrows have been constructed on the outcrops of the coal processing waste piles to control runoff (see Inspection Report 3 June 1991). The furrows have been effective. They have also given rise to some vegetative growth.

Copy of report mailed to Dan Guy/Mountain Coal; Brian Smith/OSM

Copy of report given to Joe Helfrich/DOGM; Price Field Office/DOGM

Inspector's signature *Jesse W. Kelley* No. 34

WHITE-DOGM YELLOW-OSM PINK-PERMITTEE/OPERATOR GOLDENROD-NOV FILE