



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MININGNorman H. Bangertter
GovernorDee C. Hansen
Executive DirectorDianne R. Nielson, Ph.D.
Division Director355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

September 24, 1991

CERTIFIED RETURN RECEIPT
P 074 979 131Mr. Dan Guy, Manager
Mountain Coal Company
P.O. Box 1378
Price, Utah 84501

Dear Mr. Guy:

Re: Division Order, Mountain Coal Company, C.V. Spur Mine, ACT/007/022-DO-91B,
Folder #3, Emery County, Utah

Enclosed please find a Division Order and Finding of Permit Deficiency for the C.V. Spur Mine. If in your review of this Order you have any questions, please call me or Pamela Grubaugh-Littig.

Sincerely,

A handwritten signature in cursive script that reads "Lowell P. Braxton".

Lowell P. Braxton
Associate Director, Miningjbe
Enclosurecc: Pamela Grubaugh-Littig
Joe Helfrich
Tom Munson
Bill Malencik
Henry Sauer

A:\DOLTR.91B

STATE OF UTAH
DIVISION OF OIL, GAS AND MINING

PERMITTEE

Dan Guy
C.V. Spur
Mountain Coal Company
P.O. Box 1378
Price, Utah 84501

ORDER & FINDINGS
of
PERMIT DEFICIENCY

PERMIT NUMBER ACT/007/022
DIVISION ORDER # DO-91B

PURSUANT to R614-303-212, the DIVISION ORDERS the PERMITTEE, Mountain Coal Company, to make the permit changes enumerated in the findings of permit deficiency in order to be in compliance with the State Coal Program. These findings of permit deficiency are to be remedied in accordance with R614-303-220.

Findings of Permit Deficiency
(Refuse Pile)

Regulation Citation

Diversion Design

746.212. Uncontrolled surface drainage may not be diverted over the outslope of the refuse pile. Runoff from areas above the refuse pile and runoff from the surface of the refuse pile will be diverted into stabilized diversion channels designed to meet the requirements of R614-301-742.300 to safely pass the runoff from a 100-year, 6-hour precipitation event.

Cross Sections and Maps

512.120. Surface facilities and operations as described under R614-301-521.124, R614-301-521.164, R614-301-521.165 and R614-301-521.167

512.230. Coal Mine Waste. The professional engineer experienced in the design of similar earth and waste structures must certify the design of the disposal facility according to R614-301-536.

Permit Deficiency

Refuse Pile Diversions

746.212 The diversion calculations do not clearly demonstrate that the refuse pile diversions have been designed to safely pass runoff from a 100-year, 6-hour precipitation event. Further, a refuse pile diversion west of CD-9 did not carry a designated number.

Maps & Cross Sections

512.120 The current configuration of the refuse pile is incorrectly
512.230 shown on Plates 3-2 and 3-3.

Information required to be submitted

Diversion Design

746.212 Submit in PAP format:

- 1) Calculations for all refuse pile diversions.
- 2) Revised Plate 3-2 showing each diversion and protective berm relating to the active refuse pile.

Maps and Cross Sections

512.120 Submit in PAP format:
512.230

- 1) Revised plates 3-2 and 3-3 and depict the current refuse pile area and base.
- 2) Revise and certify plate 3-3 showing current cross section refuse pile stations A to A¹.

Order

Mountain Coal Company is ordered to make the requisite permit changes in accordance with R614-303.220, and to submit a complete application for permit change to address the findings of permit deficiency within 45 days of receipt of this order. Approval by the Division must be obtained within 75 days of receipt of this order. All approvals not obtained within 75 days may result in a hindrance violation unless a request for extension has been obtained by the Director.

Ordered this ~~24th~~ day of September, 1991, by the Division of Oil, Gas and Mining.

Lawrence P. Braxton for

Dianne R. Nielson, Director
Division of Oil, Gas and Mining

jbe
cc: Tom Mitchell
Joe Helfrich
DIVISORD.FIN

DOGM JBE ACT/007/022-DO-91B #3

P 074 979 131

DAN GUY MANAGER
MOUNTAIN COAL COMPANY
PO BOX 1378
PRICE UT 84501

29
100
100
29



SENDER: Complete items 1 and 2 when additional services are desired, and complete items 3 and 4.
Put your address in the "RETURN TO" Space on the reverse side. Failure to do this will prevent this card from being returned to you. The return receipt fee will provide you the name of the person delivered to and the date of delivery. For additional fees the following services are available. Consult postmaster for fees and check box(es) for additional service(s) requested.

1. Show to whom delivered, date, and addressee's address. (Extra charge)
2. Restricted Delivery (Extra charge)


3. Article Addressed to: DAN GUY MANAGER MOUNTAIN COAL COMPANY PO BOX 1378 PRICE UT 84501	4. Article Number P 074 979 131
	Type of Service: <input type="checkbox"/> Registered <input type="checkbox"/> Insured <input checked="" type="checkbox"/> Certified <input type="checkbox"/> COD <input type="checkbox"/> Express Mail <input type="checkbox"/> Return Receipt for Merchandise
5. Signature - Address X <i>D. Gibson</i>	Always obtain signature of addressee or agent and DATE DELIVERED.
6. Signature - Agent X	B. Addressee's Address (ONLY if requested and fee paid)
7. Date of Delivery SEP 30 1991	

UNITED STATES POSTAL SERVICE
OFFICIAL BUSINESS

SENDER INSTRUCTIONS

Print your name, address and ZIP Code in the space below.

- Complete items 1, 2, 3, and 4 on the reverse.
- Attach to front of article if space permits, otherwise affix to back of article.
- Endorse article "Return Receipt Requested" adjacent to number.



PENALTY FOR PRIVATE USE, \$300

RETURN TO

Print Sender's name, address, and ZIP Code in the space below.

STATE OF UTAH
NATURAL RESOURCES
OIL, GAS, & MINING
5 TRIAD CENTER, SUITE 300
1407 LAKE CITY, UTAH 84015