



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

Permit No. ACT/007/022 Inspection Date: October 20, 1992
Permittee and/or Operators Name: Mountain Coal Company
Business Address: P.O. Box 1378 City: Price State: Utah Zip: 84501
Mine Name: C.V. Spur County: Carbon State: Utah
Type of Mining Activity: Underground Surface Other XX
Company Officials: Dan Guy State Officials: Bill Malencik
Time of Inspection: 8:00 a.m. - 1:00 p.m. Partial X Complete:
Acreage: Permitted 160 Disturbed 108 Regraded
Seeded Bonded 108 Date of Last Inspection: September 17, 1992
Weather Conditions: Clear/Temp 70's Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

| | YES | NO | N/A | NOTES |
|--|-------|-----|-----|-------|
| 1. PERMITS | () | () | () | () |
| 2. SIGNS AND MARKERS | () | () | () | () |
| 3. TOPSOIL | () | () | () | () |
| 4. HYDROLOGIC BALANCE: | | | | |
| a. STREAM CHANNEL DIVERSIONS | () | () | () | () |
| b. DIVERSIONS | (X) | () | () | (X) |
| c. SEDIMENT PONDS AND IMPOUNDMENTS | (X) | () | () | (X) |
| d. OTHER SEDIMENT CONTROL MEASURES | () | () | () | () |
| e. SURFACE AND GROUNDWATER MONITORING | () | () | () | () |
| f. EFFLUENT LIMITATIONS | () | () | () | () |
| 5. EXPLOSIVES | () | () | () | () |
| 6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL | () | () | () | () |
| 7. COAL PROCESSING WASTE | () | () | () | () |
| 8. NONCOAL WASTE | () | () | () | () |
| 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES | () | () | () | () |
| 10. SLIDES AND OTHER DAMAGE | () | () | () | () |
| 11. CONTEMPORANEOUS RECLAMATION | () | () | () | () |
| 12. BACKFILLING AND GRADING | () | () | () | () |
| 13. REVEGETATION | () | () | () | () |
| 14. SUBSIDENCE CONTROL | () | () | () | () |
| 15. CESSATION OF OPERATIONS | () | () | () | () |
| 16. ROADS | | | | |
| a. CONSTRUCTION | () | () | () | () |
| b. DRAINAGE CONTROLS | () | () | () | () |
| c. SURFACING | () | () | () | () |
| d. MAINTENANCE | (X) | () | () | (X) |
| 17. OTHER TRANSPORTATION FACILITIES | () | () | () | () |
| 18. SUPPORT FACILITIES | | | | |
| UTILITY INSTALLATIONS | () | () | () | () |
| 19. AVS Check | () | () | () | () |

Permit No. ACT/007/022 Inspection Date October 20, 1992

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments -

No coal trucks were observed coming into the loadout. This is attributable to the fact that the mine is idle that supports the loadout (Trail Mountain Mine). Further, the mine is in the process of being sold and a permit transfer application has been submitted to the Division. The loadout, permit, and operations at the C.V. Spur will remain with Mountain Coal since the contract of sale did not include the Spur Loadout.

4b. Diversions -

The natural diversion west of the railroad tracks and east of the refuse pile was observed. The operators had placed wire/rock drainage regrade devices in the drainage to minimize erosion as suggested by the Division. Such devices have also been installed in other man made diversions in the past.

Permit No. ACT/007/022 Inspection Date October 20, 1992

(Comments are Numbered to Correspond with Topics Listed Above)

4c. Sediment Pond and Impoundments -

Pond 6 contained a significant amount of water although no evidence of discharge through the spillway was detected. Other ponds were dry except for pond 5 and it contained about a foot of runoff.

16d. Roads -

All primary roads had been watered the morning prior to the inspection.

Copy of report:

Mailed to: Mountain Coal CompanyMailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)Filed to: PFODate: October 22, 1992

Inspector's Signature and Number:



#26

Wm. J. Malencik