

0005



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangerter  
Governor

Dee C. Hansen  
Executive Director

Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

INSPECTION DATE & TIME: August 18, 1992  
1:30 pm to 3:50 pm

Permittee and/or Operator's Name: Mountain Coal Company  
Business Address: P.O. Box 1378, Price, Utah 84501  
Mine Name: C.V. Spur Loadout Permit Number: ACT/007/022  
Type of Mining Activity: Underground Surface Other X  
County: Carbon Company Official(s): Burk Biersdorf  
State Officials(s): Ken Wyatt  
Federal Official(s): None  
Partial: X Complete None Date of last Inspection: July 14 & 16, 1992  
Weather Conditions: Clear, hot 90's  
Acreage: Permitted-160 Disturbed-108 Regraded Seeded Bonded-108  
Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	( )	( )	(X)
2. SIGNS AND MARKERS	(X)	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( )	( )	( )
b. DIVERSIONS	(X)	( )	( )	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	( )	( )	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	( )	( )	(X)
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	(X)	( )	( )	(X)
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/022

DATE OF INSPECTION: 08/18/92

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permits

This inspection included an AVS check. The mine permit examined at the mine office listed Mountain Coal Company as the operator of the C.V. Spur facility. The identification sign listed the operator as:

Mountain Coal Company  
P.O. Box 1378  
Price, UT 84501  
(801) 748-2140

4b. Diversions

The diversions draining from the southern end of the property east of the topsoil stockpile have been maintained by installing additional rock/wire check dams.

4c. Sediment Ponds and Impoundments

Water from the wash plant was flowing into pond 6. The gravel dikes between cells of pond 6 were recently replaced. This allows better flow between cells. The gravel material excavated during this work was stockpiled near the wash plant. Mr. Biersdorf indicated that the gravel would be used as road surfacing material within the disturbed area.

Sediment pond 5 contained a small amount of water. No ponds were discharging at this time.

4d. Other Sediment Control Measures

The silt fence along the northern end of the soil stockpile area had new fabric recently installed.

7. Coal Processing Waste

Very little waste rock has been generated from the wash plant and disposed of at the refuse pile. The refuse pile surface drainage had functioned as designed. Evidence that water had flowed along the east side of the pile was observed. All drainage flowed into the downslope culvert and to pond 5.

Copy of this Report:

Mailed to: Dan Guy (MCC), Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: \_\_\_\_\_

*Ken Wyatt*

#7 Date: 08/21/92