


0004

ACT/007/033-87A
#2



ANDALEX
RESOURCES, INC.
Tower Division

P.O. BOX 902
PRICE, UTAH 84501
PHONE (804) 637-5385
TELEX 381 530 ANDALEX PRIC

September 17, 1987

RECEIVED
SEP. 21 1987

DIVISION OF OIL
GAS & MINING

State of Utah
Department of Natural Resources
Division of Oil, Gas and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Attention: D. Wayne Hedberg

Dear Mr. Hedberg:

Pursuant to your September 10, 1987 letter regarding Sediment Pond inspection frequency, Andalex Resources has opted for the time being not to use the carbonaceous rock material for rip rap at pond inlets. Rather, all the pond inlets have been equipped with half culverts, 24" in diameter with inlet arpons attached. The inlet culverts then discharge onto 42" conveyor belt which runs to the botton of the ponds. This work was completed on 9/11/87.

Should Andalex in the future desire to use the rock material for rip rap, we will provide evidence that it meets specifications of 817.72 (b)(1)(4). Hopefully on the basis of this letter you can now approve our change request .

Thank you.

Sincerely,

Michael W. Glasson
Senior Geologist
Western Operations

FILE COPY

cc: Jim Fricke, Salt Lake DOGM
Bill Malencik, Price DOGM