



John *John* *John*

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Feb. 18, 1988
10:30 a.m. to 12:30 p.m.

Permittee and/or Operators Name: Andalex Resources Inc.
Business Address: P.O. Box 902 Price, Utah 84501
Mine Name: Wildcat Prep Plant Permit Number: PRO/007/033
Type of Mining Activity: Underground Surface Other X
County: Carbon
Company Official (s): John Pappas
State Official(s): Bill Malencik, Daron Haddock, John Whitehead
Partial: X Complete: Date of Last Inspection: Jan. 7, 1988
Weather Conditions: Partly cloudy, cold
Acreage: Permitted Disturbed 60 Regraded Seeded Bonded
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: PRO/007/033

DATE OF INSPECTION Feb. 18, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

The preparation plant was partially covered with snow. No problems were detected on this partial inspection.

1. PERMITS:

The operator submitted a formal application and a draft MRP to DOGM the end of December 1987.

4b. DIVERSIONS:

Because of the cold weather, no snowmelt nor runoff was evident. The operator stated that the ditch next to the lump coal pile would be realigned and culvert installed this spring.

4c. SEDIMENT PONDS:

Sediment ponds A-F were casually observed and no problems detected. From the snow banks remaining, snow removed from the roads had been stockpiled so that the snowmelt runoff would drain into a pond and/or treatment facility.

All sediment ponds showed evidence of the mulch that had been installed on all sediment embankments and retained in place. Sediment pond E is scheduled to be enlarged this spring.

Copy of this Report:

Mailed to: Mike Glasson, Andalex

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM

Filed: PFO

Inspectors Signature and Number: William J. Malencik #26 Date: Feb. 18, 1988