

0004



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

October 6, 1988

Mr. Michael Glasson
Andalex Resources, Inc.
P. O. Box 902
Price, Utah 84501

Dear Mr. Glasson:

Re: Powerline Modification, Andalex Resources, Inc., Wildcat
Loadout Facility, ACT/007/033, Folder #2, Carbon County,
Utah

On September 13, 1988, Clark Johnson of the U.S. Fish and Wildlife Service (USFWS) examined the powerline between the substation and Wildcat Loadout Facility. Attached is a copy of his letter. The USFWS recommends that powerpoles be modified by ground wire gapping. This minimizes the possibility of a raptor making simultaneous contact between an energized conductor and ground while continuing to provide lightning protection.

You are hereby directed to complete the modification as requested by November 30, 1988. The Division will perform a follow-up inspection to document compliance shortly thereafter.

Sincerely,

A handwritten signature in cursive script that reads "Brent A. Stettler".

Brent A. Stettler
Reclamation Biologist

djh
Attachment
cc: J. Whitehead
WP+/18