

0013

RECEIVED
APR 24 1989

PRO
File # 007/033 #2

2890
UTU-48027
(U-066)

DIVISION OF
OIL, GAS & MINING

Moab District
Price River Resource Area
900 North 700 East
Price, Utah 84501

Mr. Michael Glasson
Andalex Resources Incorporated
P. O. Box 902
Price, Utah 84501

APR 19 1989

Dear Mr. Glasson:

We have received reports from the Utah Division of Wildlife Resources and your personnel at Wildcat that at least 12 deer have been caught and killed in the fence surrounding your coal loadout facility this winter. Apparently, deer in their attempt to jump the fence are caught between the top two wires. We would like to see the fence modified so that deer are able to safely jump the fence. This can be accomplished by removing the middle wire. We feel that the requested modification will significantly reduce the deer mortality as a result of the fence.

Please contact Mark Mackiewicz if you have any questions at 637-4584.

Sincerely yours,

MARK E. BAILEY

Area Manager

cc: Brent Stetler
UDOGM

Mackiewicz:sw:4/19/89
Wang 0104M