



0012

ANDALEX
RESOURCES, INC.
Tower Division

P.O. BOX 902
PRICE, UTAH 84501
PHONE (801) 637-5385
TELECOPIER (801) 637-8860

KS *orig mine file*
de Linner

6-1007/1990

Mr. Don A Ostler, P.E.
Executive Secretary
State of Utah
Department of Health
Division of Environmental Health
P.O. Box 16690
Salt Lake City, UT 84116-0690
Attn: Mike Herkimer

RECEIVED
JAN 11 1990
DIVISION OF
OIL, GAS & MINING

re: UTG040008 (Pinnacle Mine)

Dear Mr. Ostler:

It has come to my attention that the permit issued to us in June of 1989 may need to be supplemented.

We have recently completed the earthwork portion of the construction associated with a new minesite which we are calling the Aberdeen Mine. It is located in the same canyon but downstream from our Pinnacle Mine. Until now, our NPDES permit for this facility consisted of two outfall locations, shown on the enclosed map as 001 and 002. As a result of this new mine facility a new sedimentation pond has been constructed and is shown on the map as 003. Its location is 39° 41' 59" by 110° 46' 12". Outfall 001 is a sedimentation pond and 002 is an occasional mine discharge which your office approved in May of 1984.

To date there has never been a discharge from the sedimentation pond outfall 001, even though we have experienced a 100 year 24 hour precipitation event here at the mine. We do not desire to have any parameters of the General Coal Mining permit changed, simply to add the new outfall location.

Please call me should any questions arise.


Thank you for your attention to this matter.

Sincerely,
Michael W. Glasson
Michael W. Glasson
Senior Geologist

MWG/jo

Enclosure

cc: ✓ Susan Linner, UDOGM w/enc1
Daron Haddock, UDOGM w/enc1



DEADMAN CANYON
7.5 MINUTE
QUADRANGLE