




0005

**ANDALEX**  
**RESOURCES, INC.**  
Tower Division

P.O. BOX 902  
PRICE, UTAH 84501  
PHONE (801) 637-5385  
TELECOPIER (801) 637-8860

920

June 1, 1992



State of Utah  
Department of Natural Resources  
Division of Oil, Gas and Mining  
355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203

Attn.: Pam Littig, Permit Supervisor

Re.: ACT 007/033, Disturbed Area Culverts

Dear Ms. Littig,

# 2

It has come to our attention that two disturbed area culverts (C-28 and C-29) at the Wildcat Loadout have become essentially ineffective. Due to heavy equipment traffic, these two culverts, located in disturbed ditches D-7 and D-8 respectively, are difficult, at best, to maintain. Andalex proposes to remove these culverts and replace them with extensions of D-7 and D-8. Andalex is committed to the maintenance of these ditches and can foresee an improvement in maintenance and drainage control through this action.

I have enclosed four (4) copies each of Plate 1, depicting the removal of these culverts alongside of PR-1. Please advise us of your decision as we desire to incorporate this improvement as soon as possible.

Thank you for your consideration.

Sincerely,

Michael W. Glasson  
Senior Geologist

MWG/as

cc: File