

0010



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

gh

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: Complete: XX Exploration:

Inspection Date & Time: 9/20/95 - 10:00a.m.-2:00p.m.

Date of Last Inspection: 8/21/95

Mine Name: Wildcat Loadout County: Carbon Permit Number: ACT/007/033
Permittee and/or Operator's Name: Andalex Resources, Inc.
Business Address: P.O. Box 902, Price, Utah 84501
Type of Mining Activity: Underground Surface Prep. Plant XXX Other
Company Official(s): Mike Glasson
State Officials(s): Stephen J. Demczak Federal Official(s):
Weather Conditions: 70's Clear
Existing Acreage: Permitted- 100 Disturbed- 63.7 Regraded- Seeded- Bonded- 60
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/ Phase II/ Final Bond Release/ Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 4 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; CONSTRUCTION/MAINTENANCE/SURFACING; DRAINAGE CONTROLS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK; AIR QUALITY PERMIT; BONDING & INSURANCE.



INSPECTION REPORT
(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/007/033

DATE OF INSPECTION: 9/20/95

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT -

- a) The permittee will be submitting an amendment to the Division to update the surface facility map for Wildcat Loadout.
- b) The haul roads were P.E. certified on February 28, 1995.
- c) The UPDES self monitoring of sediment ponds showed no discharging for second quarter for 1995.
- d) The mining permit was signed by the director of the Division and the permittee on May 9, 1995.
- e) The permittee reported that all watering sites were dry during first and second quarter of 1995.
- f) The bond has changed from 60 acres to 63.7 acres on January 9, 1995.
- g) The insurance will expire~~s~~ on June 1, 1996.
- h) The refuse piles inspections by the operator were taken by a P.E. for first and second quarter of 1995.

4A. DIVERSIONS -

The diversions throughout the property were re-graded and appear to be functioning as designed. There were no signs of water breaching the ditches.

INSPECTION REPORT
(Continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/007/033

DATE OF INSPECTION: 9/20/95

(Comments are Numbered to Correspond with Topics Listed Above)

4B. SEDIMENT PONDS -

The sediment ponds were dry and would not likely discharge any water in the near future. The ponds showed no signs of erosion of the embankments and appeared to be stable with no hazardous conditions existing.

4C. OTHER SEDIMENT CONTROL MEASURES -

The permittee uses straw bales as the alternate sediment control measures throughout the property. The straw bales were functioning as required by catching silt behind them.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Mike Glasson (Andalex)

Donna Griffin (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: September 21, 1995

Inspector's Signature: _____

Stephen J. Demczak

#39