



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: XX Complete: Exploration:

Inspection Date & Time: 8/21/95 / 8:00a.m.-12:00p.m.

Date of Last Inspection: 7/14/95

Mine Name: Wildcat Loadout County: Carbon Permit Number: ACT/007/033

Permittee and/or Operator's Name: Andalex Resources, Inc.

Business Address: P.O. Box 902, Price, Utah 84501

Type of Mining Activity: Underground Surface Prep. Plant XXX Other

Company Official(s): Mike Glasson

State Officials(s): Stephen J. Demczak Federal Official(s):

Weather Conditions: Warm 80's

Existing Acreage: Permitted- 100 Disturbed- 63.7 Regraded- Seeded- Bonded- 60

Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-

Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture

Reclamation (Phase I/Phase II/Final Bond Release/Liability Year)

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: 1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; 2. SIGNS AND MARKERS; 3. TOPSOIL; 4. HYDROLOGIC BALANCE; 5. EXPLOSIVES; 6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; 7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; 8. NONCOAL WASTE; 9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; 10. SLIDES AND OTHER DAMAGE; 11. CONTEMPORANEOUS RECLAMATION; 12. BACKFILLING AND GRADING; 13. REVEGETATION; 14. SUBSIDENCE CONTROL; 15. CESSATION OF OPERATIONS; 16. ROADS; 17. OTHER TRANSPORTATION FACILITIES; 18. SUPPORT FACILITIES/UTILITY INSTALLATIONS; 19. AVS CHECK (4th Quarter-April, May, June) (date); 20. AIR QUALITY PERMIT; 21. BONDING & INSURANCE.



INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/033

DATE OF INSPECTION: 8/21/95

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT -

The permittee will be submitting an amendment for installing culverts to transport water from the top coal stockpile pad to the ditch below which in turn directs water to the sediment ponds. There has been failure of the outslopes of the upper pad with water breaching the MSHA berm. The breaching occurred under heavy thunder storm rains.

3. TOPSOIL PILES -

The new topsoil pile located above the rail loadout is comprised mostly of weed vegetation. The pile was seeded under the guidance of the Division personnel. The grasses are being choked out by unwanted vegetation. The topsoil pile needs to be treated with weed spray for the seed mix vegetation to be established.

4A. DIVERSIONS -

The diversions were spot inspected. Due to the thunder storm, there are several ditches that need sediment to be cleaned out of them. The ditches were still functioning but sediment has started to build-up.

4B. SEDIMENT PONDS -

The sediment ponds were inspected with small amounts of water contained in the ponds. There were no signs of erosion of the inlets, outlets, or embankments. No hazardous conditions could be seen.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Mike Glasson (Andalex)

Donna Griffin (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: August 23, 1995

Inspector's Signature: 

Stephen J. Demczak

#39