



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

Partial: XXX Complete: Exploration:
Inspection Date & Time: 6/26/2000 / 9:00a.m.-2:00p.m.
Date of Last Inspection: 5/25/2000

Mine Name: Wildcat Loadout County: Carbon Permit Number: ACT/007/033
Permittee and/or Operator's Name: Andalex Resources, Inc.
Business Address: P. O. Box 902, Price, Utah 84501
Type of Mining Activity: Underground Surface Prep. Plant XXX Other
Company Official(s): None
State Officials(s): Stephen J. Demczak Federal Official(s): None
Weather Conditions: Warm, 70's
Existing Acreage: Permitted-100 Disturbed-63.7 Regraded- Seeded- Bonded-60
Increased/Decreased: Permitted- Disturbed- Regraded- Seeded- Bonded-
Status: Exploration/ XXX Active/ Inactive/ Temporary Cessation/ Bond Forfeiture
Reclamation (Phase I/Phase II/ Final Bond Release/ Liability Year)

PH

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: EVALUATED, N/A, COMMENTS, NOV/ENF. Rows include: PERMITS, CHANGE, TRANSFER, RENEWAL, SALE; SIGNS AND MARKERS; TOPSOIL; HYDROLOGIC BALANCE; DIVERSIONS; SEDIMENT PONDS AND IMPOUNDMENTS; OTHER SEDIMENT CONTROL MEASURES; WATER MONITORING; EFFLUENT LIMITATIONS; EXPLOSIVES; DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES; COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS; NONCOAL WASTE; PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES; SLIDES AND OTHER DAMAGE; CONTEMPORANEOUS RECLAMATION; BACKFILLING AND GRADING; REVEGETATION; SUBSIDENCE CONTROL; CESSATION OF OPERATIONS; ROADS; CONSTRUCTION/MAINTENANCE/SURFACING; DRAINAGE CONTROLS; OTHER TRANSPORTATION FACILITIES; SUPPORT FACILITIES/UTILITY INSTALLATIONS; AVS CHECK (4th Quarter-April, May, June) (date); AIR QUALITY PERMIT; BONDING & INSURANCE.

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/033

DATE OF INSPECTION: 6/26/2000

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS -

Identification signs meet the requirements of the R645 coal rules. The perimeter markers were spot-checked and are located about the perimeter of the disturbed area. The Wildcat loadout is not located in close proximity to a stream.

3. TOPSOIL -

The topsoil piles were inspected with no signs of wind or water erosion. These piles are protected by berms and vegetation. All piles have proper signs for identification.

4A. DIVERSIONS -

The diversions were spot-checked and were found to comply with the requirements of the mining and reclamation plan and the R645 coal rules. Most of the diversions have been cleaned since the last inspection.

4B. SEDIMENT PONDS -

The sediment ponds were not discharging during the inspection; water levels are indicative that they will not likely discharge in the near future. There were no signs of hazardous conditions noted during the inspection of the various ponds.

4C. OTHER SEDIMENT CONTROL MEASURES -

The Wildcat loadout facility uses straw bales as its method of alternate sediment control. These areas were spot-inspected and were found to be in compliance with the R645 coal rules. Some straw bales will need to be changed in the near future, due to deterioration.

5. EXPLOSIVES -

There are no explosive storage magazines on the property.

7. REFUSE PILES -

The refuse pile was inspected with no hazardous conditions being noted.

8. NON-COAL WASTE -

The area was clear of non-coal waste material.

18. SUPPORT FACILITIES -

There were no additional support facilities noted.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Mike Glasson (Andalex) Henry Austin (OSM)
Given to: Pam Grubaugh-Littig (DOGM) Filed to: Price Field Office
Date: June 26, 2000

Inspector's Signature:  #39
Stephen J. Demczak