



**GARY R. HERBERT**  
Governor  
**GREG BELL**  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

**MICHAEL R. STYLER**  
Executive Director

### Division of Oil, Gas and Mining

**JOHN R. BAZA**  
Division Director

# Inspection Report

Permit Number:	C0070033
Inspection Type:	PARTIAL
Inspection Date:	Wednesday, May 05, 2010
Start Date/Time:	5/5/2010 8:02:00 AM
End Date/Time:	5/5/2010 8:40:00 AM
Last Inspection:	Wednesday, April 14, 2010

Representatives Present During the Inspection:	
Company	Scott Dimick Superintendent
OGM	Pete Hess Environmental Scientist III

Inspector: Pete Hess, Environmental Scientist III

Weather: Cool, 50's F. High clouds.

InspectionID Report Number: 2345

Accepted by: jhelfric  
5/6/2010

Permittee: **ANDALEX RESOURCES INC TOWER DIVISION**  
Operator: **ANDALEX RESOURCES INC TOWER DIVISION**  
Site: **WILDCAT LOADOUT**  
Address: **6750 AIRPORT RD, PO BOX 902 PRICE UT 84501**  
County: **CARBON**  
Permit Type: **PERMANENT COAL PROGRAM**  
Permit Status: **ACTIVE**

#### Current Acreages

100.00	<b>Total Permitted</b>
78.45	<b>Total Disturbed</b>
	<b>Phase I</b>
	<b>Phase II</b>
	<b>Phase III</b>

#### Mineral Ownership

- Federal
- State
- County
- Fee
- Other

#### Types of Operations

- Underground
- Surface
- Loadout
- Processing
- Reprocessing

#### Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee has notified the Division that it may be selling, or temporarily idling the Wildcat Loadout facility at the end of May, 2010. Intermountain Power Agency / Los Angeles Department of Water and Power would be the likely purchaser of the property. A transfer of the permit to a new owner is being discussed with Division senior managers. Division Order DO-04, Design Drawings and Specifications, remains pending at this facility. The Permittee needs to address several deficiencies identified by the DOGM and re-submit this application.


Inspector's Signature:

Pete Hess, Environmental Scientist III  
Inspector ID Number: 46

Date

Wednesday, May 05, 2010

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.  
telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov



**REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS**

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

**1. Permits, Change, Transfer, Renewal, Sale**

As noted above, a possible permit transfer from UtahAmerican Energy, Inc., (the possible seller) to a new owner (possibly Intermountain Power Agency) may be pending. A decision from Murray Energy Corporation is expected by May 30, 2010.

**4.d Hydrologic Balance: Water Monitoring**

All snow has melted off the permit area, as well as the surrounding undisturbed area. No flow was observed in Wildcat Wash. Pond "C" contained a small amount of water; all other ponds were dry.

**4.e Hydrologic Balance: Effluent Limitations**

No ponds were close to discharge.

**7. Coal Mine Waste, Refuse Piles, Impoundments**

The waste rock pile is well graded, on both the active lift and the out slopes. No water is retained on the pile. Adjacent ditches appeared capable of functioning as designed. The active lift of the refuse facility did not appear to contain any noncoal waste.

**16.a Roads: Construction, Maintenance, Surfacing**

The Permittee has spread the snow and road material accumulations which occur as part of the snow removal process at the site to let the water melt off. Carbonaceous material which remains will be collected and disposed of on the waste rock pile.

**16.b Roads: Drainage Controls**

Road drainage ditches have been re-worked.

**22. Other**

The Division completed the review of the 2009 Annual Report information (Task ID # 3523) on April 12, 2010.