



GARY R. HERBERT
Governor

SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

June 25, 2014

James A. Hewlett, Resident Agent
Intermountain Power Agency
10653 South River Front Parkway, Suite 120
South Jordan, Utah 84095

Subject: 2013 Annual Report Review Completion, Wildcat Loadout, C/007/0033, Task ID# 4574

Dear Mr. Hewlett:

The Division staff has completed the review of the 2013 Annual Report. Enclosed is a copy of the review with each reviewer's comments completed on June 25, 2014.

Thank you for your diligence in completing the Annual Report. If you have any questions, please call me at (801) 538-5325.

Sincerely,

Daron R. Haddock
Coal Program Manager

DRH/sqs
Enclosure
O:\007033.WCL\WG4574\ReviewCompletionLetter.doc

Print Form

Submit by Email

Reset Form

Annual Report

This Annual Report shows information the Division has for your mine. Submit the completed document and any additional information identified in the Appendices to the Division by the date specified in the cover letter. During a complete inspection an inspector will check and verify the information.

GENERAL INFORMATION

Company Name	Intermountain Power Agency	Mine Name	Wildcat Loadout
Permit Number	C/007/0033	Permit expiration Date	
Operator Name	Wild West Equipment & Hauling, LLC	Phone Number	+1 (435) 472-3988
Mailing Address	P.O. Box 1	Email	kit@emerytelcom.net
City	Price		
State	UT	Zip Code	84501

DOGM File Location or Annual Report Location

- Excess Spoil Piles Required Not Required
- Refuse Piles Required Not Required
- Impoundments Required Not Required

REFUSE PILE CERTIFICATION (INCLUDED)

SEDIMENT POND CERTIFICATION (INCLUDED)

Other:

OPERATOR COMMENTS

REVIEWER COMMENTS

- Met Requirements Did Not meet Requirements

The operator included in the annual report quarterly inspection reports of the refuse pile, inspected and PE certified by Tom Paluso. No instabilities were reported from these inspections. Also included in the report are the PE certified inspection reports of the sediment ponds and impoundments. During inspections quarterly inspections of refuse piles and ponds are reviewed. (ad)

COMMITMENTS AND CONDITIONS

The Permittee is responsible for ensuring annual technical commitments in the Mining and Reclamation Plan and conditions accepted with the permit are completed throughout the year. The Division has identified these commitments below and has provided space for you to report what you have done during the past year for each commitment. If additional written response is required, it should be filed as an attachment to this report.

Title: COAL FINE ACCUMULATION MONITORING

Objective: To minimize coal fine accumulations on undisturbed ground within the disturbed area boundary. This area did not have topsoil salvaged, but was vacuumed, disced, mulched and seeded in September 2010. Please provide the depth of the new accumulation if present. Please provide the photo locations on a map. Additionally, please create a grid system on a plan view map of the fines recovery area and report the percentage of area covered by fines in each area and the depth of the fines, similar to Figure 1 / Plate 1 in Appendix "P" of the MRP which plotted coal fines depth prior to fines recovery.

Frequency: Quarterly

Status: Ongoing

Reports: Monitoring protocol, location of observations, digital photographs and results to be filed with the Annual report.

Citation: MRP, Appendix P, Item 7

Operator Comments

SEE "WILDCAT COAL FINES ISSUE, DIVISION ORDER-04 (WIND BLOWN FINES), QUARTERLY MONITORING REPORTS (INCLUDED)

Reviewer Comments Met Requirements Did Not Meet Requirements

Reviewed by Priscilla Burton on 4/10/2014. The coal fine accumulation on undisturbed soil within the permit area has been monitored quarterly in a systematic manner. The average depth of coal fine accumulation in the north was reported to vary between a quarter inch to 3/4 inch, with locations N 5 and N8 having between 2 and 5 inches of accumulation. The third quarter reporting indicates that above average precipitation in July, August and September 2013 moved the sediments, burying some and concentrating others. This likely accounts for the accumulation upwards of six inches of coal fines in the vicinity of N5 (at the silt fence) observed on January 24, 2014. I recommend that future monitoring follow the visual method assessing percent cover as outlined in Schjoeneberger, P.J., Wysocki, D.A., Benham, E.C. and Broderson, W.D. 1998. Field book for describing and sampling soils. Natural Resources Conservation Service, USDA, National Soil Survey Center, Lincoln, NE. There is evidence of fines in the reference area and some thistle in the NE portion of previous cleaning efforts. The permittee is currently addressing these issues. A percent cover and woody species density survey of the reference area will be conducted in 2014 to determine if the fines have had any impact on the vegetation in the reference area. The thistle was sprayed by hand in June.

FUTURE COMMITMENTS AND CONDITIONS

The following commitments are not required for the current annual report year, but will be required by the permittee in the future as indicated by the "status" field. These commitments are included for information only, and do not currently require action. If you feel that the commitment is no longer relevant or needs to be revised, please contact the Division.

Title: PROTECTION OF TOPSOIL

Objective: To protect topsoil

Frequency: Prior to construction of Pond G

Status: Future commitment (Prior to construction of Pond G).

Reports: Monitor soil salvage from the "mechanical clean-up area" east of PR 5. Provide an as-built showing dimensions and volume contained in Topsoil Pile A.

Citation: MRP, Section R645-301-212, and Appendix P, Item 2, Item 4 and Figure 2.

OPERATOR COMMENTS (OPTIONAL)

N/A AT THIS TIME

REVIEWER COMMENTS

REPORTING OF OTHER TECHNICAL DATA

Please list other technical data or information that was not included in the form above, but is required under the approved plan, which must be periodically submitted to the Division.

Please list attachments:

Reviewer Comments

MAPS

Copies of mine maps, current and up-to-date, are to be provided to the Division as an attachment to this report in accordance with the requirements of R645-301-525.240. The map copies shall be made in accordance with 30 CFR 75.1200 as required by MSHA. Mine maps are not considered confidential.

Map Name	Map Number	Included		Confidential	
		Yes	No	Yes	No
		<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
		<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Reviewer Comments Met Requirements Did Not Meet Requirements