

0003



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

10-2-87

File

SL

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Oct. 27, 1987
9:30 a.m. to 10:30 a.m.

Permittee and/or Operators Name: Soldier Creek Coal Company
Business Address: P.O. Box I Price, Utah 84501
Mine Name: Banning Siding Prep Plant Permit Number: PRO/007/034
Type of Mining Activity: Underground Surface Other X
County: Carbon
Company Official (s): Tom Paluso (Soldier Creek), Boyd Rhodes (Savage Bros)
State Official(s): Holland Shepherd (DOGM)
Partial: X Complete: Date of Last Inspection: Sept. 23, 1987
Weather Conditions: Sunny and clear
Acreage: Permitted n/a Disturbed n/a Regraded n/a Seeded n/a Bonded n/a
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: PRO/007/034

DATE OF INSPECTION Oct. 27, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

4d. OTHER SEDIMENT CONTROLS:

1. The settling basin facility contains very little water at this time. The site experienced steady rains last weekend but was not adversely impacted, and water accumulation in the settling basin was minor.

2. Straw bales, which have been installed at the south end of the site, have been damaged by cattle. No drainage has moved beyond these bales; no noncompliance exists at this time. The operator indicated that the straw bales will be replaced by silt fence by the beginning of next month.

Copy of this Report:

Mailed to: Allen Childs, Soldier Creek (10-28-87); Brian Smith, OSM

Given to: Joe Helfrich, DOGM

Inspectors Signature and Number: Holland Shepherd #9 Date: Oct. 28, 1987