

0010

10-2-87



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Ych 54

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84143 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 5-18-87
2:00 to 3:00 p.m.

Permittee and/or Operators Name: Soldier Creek Coal Company
Business Address: P.O. Box I Price, Utah 84501
Mine Name: Banning Siding Permit Number: PRO/007/Q34
Type of Mining Activity: Underground Surface Other Preparation Plant
County: Carbon
Company Official (s): Chris Allan
State Official(s): Holland Shepherd
Partial: X Complete: Date of Last Inspection: 4-23-87
Weather Conditions: cloudy, warm
Acreage: Permitted n/a Disturbed n/a Regraded 0 Seeded 0 Bonded 0
Enforcement Action: none

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER PRO/007/034

DATE OF INSPECTION 5-18-87

(Comments are Numbered to Correspond with Topics Listed Above)

4.c. Sediment Pond:

The operator's sediment pond was nearly empty upon inspection. Some runoff was evident from spring rains which occurred the previous weekend.

4.d. Other Sediment Controls:

The operator was instructed to maintain the site's perimeter berm in two locations along the fence. One location is at the south end of the compound, the other is along the west side. Measures taken would be preventative at both locations. No noncompliance was determined.

Copy of this Report:

Mailed to: Chris Allen, Donna Griffin
Given to: Joe Helfrich

Inspectors Signature and Number: Holland Shepherd #9 Date: 5-20-87