



0010

STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

**INSPECTION REPORT**

INSPECTION DATE & TIME: August 10, 1988  
9:45-11:15 a.m.

Permittee and/or Operators Name: Soldier Creek Coal Co.  
Business Address: P.O. Box I Price, Utah 84501  
Mine Name: Banning Siding Loadout Permit Number: PRO/007/034 7/65  
Type of Mining Activity: Underground Surface Other XX  
County: Carbon State: Utah  
Company Official(s): Chris Allen  
State Official(s): Daron Haddock  
Partial: XX Complete: \_\_\_\_\_ Date of Last Inspection: July 20, 1988  
Weather Conditions: Sunny, hot and dry  
Acreage: Pending Permit 36 Disturbed 25.6 Regraded \_\_\_\_\_ Seeded \_\_\_\_\_ Bonded \_\_\_\_\_  
Enforcement Action: None

**COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS**

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. <u>PERMITS</u>	<u>( X )</u>	<u>( )</u>	<u>( )</u>	<u>( X )</u>
2. <u>SIGNS AND MARKERS</u>	<u>( X )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
3. <u>TOPSOIL</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
4. <u>HYDROLOGIC BALANCE:</u>				
a. <u>STREAM CHANNEL DIVERSIONS</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
b. <u>DIVERSIONS</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
c. <u>SEDIMENT PONDS AND IMPOUNDMENTS</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
d. <u>OTHER SEDIMENT CONTROL MEASURES</u>	<u>( X )</u>	<u>( )</u>	<u>( )</u>	<u>( X )</u>
e. <u>SURFACE AND GROUNDWATER MONITORING</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
f. <u>EFFLUENT LIMITATIONS</u>	<u>( X )</u>	<u>( )</u>	<u>( )</u>	<u>( X )</u>
5. <u>EXPLOSIVES</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
6. <u>DISPOSAL OF DEVELOPMENT WASTE AND SPOIL</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
7. <u>COAL PROCESSING WASTE</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
8. <u>NONCOAL WASTE</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
9. <u>PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES</u>	<u>( X )</u>	<u>( )</u>	<u>( )</u>	<u>( X )</u>
10. <u>SLIDES AND OTHER DAMAGE</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
11. <u>CONTEMPORANEOUS RECLAMATION</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
12. <u>BACKFILLING AND GRADING</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
13. <u>REVEGETATION</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
14. <u>SUBSIDENCE CONTROL</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
15. <u>CESSATION OF OPERATIONS</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
16. <u>ROADS</u>				
a. <u>CONSTRUCTION</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
b. <u>DRAINAGE CONTROLS</u>	<u>( X )</u>	<u>( )</u>	<u>( )</u>	<u>( X )</u>
c. <u>SURFACING</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
d. <u>MAINTENANCE</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
17. <u>OTHER TRANSPORTATION FACILITIES</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>	<u>( )</u>
18. <u>SUPPORT FACILITIES</u>				
<u>UTILITY INSTALLATIONS</u>	<u>( X )</u>	<u>( )</u>	<u>( )</u>	<u>( X )</u>

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: PRO/007/034

DATE OF INSPECTION August 10, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS:

The operator has submitted the Permit Application Package and is now in the public notification period. The required notice is being published in the Price Sun Advocate.

4d. OTHER SEDIMENT CONTROL MEASURES:

The berms along the North and West fence line have been built up in order to contain the surface drainage to the site. An inspection of the silt fences and straw bales at the south end of the property showed them to be functioning properly. A recent thunderstorm appeared to have been contained to the treatment facilities.

4f. EFFLUENT LIMITATIONS:

No water was being discharged from the site during this inspection.

9. PROTECTION OF FISH WILDLIFE AND RELATED ENVIRONMENTAL VALUES:

Antelope were spotted south of the property and antelope tracks were noted next to the property fence.

16b. ROAD DRAINAGE CONTROLS:

The culverts under the main haul road are clear and functioning properly.

18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS:

Some of the feeders under the main coal storage pile have settled and will no longer feed coal to the train loading conveyor. Some of the coal is being pushed to the side so that work can be done on the feeders. Any disturbance will be limited to the coal pile area which will be well within the disturbed boundaries.

Copy of this Report:

Mailed to: Chris Allen, SCCC

Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM

Filed to: PFO

Inspectors Signature and Number: Daron R. Haddock #28 Date: August 11, 1988