



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Handwritten initials/signature

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: July 5, 1990
2:00 p.m. - 3:30 p.m.

Permittee and/or Operators Name: Soldier Creek Coal Co./Savage Coal Service
Business Address: P.O. Box I Price, Utah 84501
Mine Name: Banning Siding Loadout Permit Number: ACT/007/034
Type of Mining Activity: Underground Surface Other Loadout
County: Carbon State: Utah
Company Official(s): Dave Spillman
State Official(s): Johnny Pappas, Bill Malencik
Partial: XX Complete: Date of Last Inspection: June 13, 1990
Weather Conditions: Overcast and calm
Acreage: Permitted 36.83 Disturbed 26.35 Regraded Seeded Bonded 21.4
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	(X)
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/034

DATE OF INSPECTION July 5, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

General:

Dave Spillman was on vacation at the time of this partial inspection. Barry Prettyman, therefore assisted us with the inspection.

2. Signs and Markers:

The wire that supports the ID sign has been repaired.

4. Hydrologic Balance:

c. Sediment Ponds and Impoundments.

The sediment pond looked stable and no problems noted.

d. Other Sediment Control Measures.

The berms surrounding the site are in good condition. The operators cleaned the locations where coal fines had accumulated on the inside of the berm. The silt fences appear to be in good working condition with no apparent short circuiting.

16. Roads:

b. Drainage Controls.

The culverts were clear and able to function properly.

Mailed to: Dave Spillman (SCCC)

Mailed to SLC for: Brian Smith (OSM), Joe Helfrich (DOGM)

Filed to: PFO

Inspectors Signature and Number *Johnny Pappas* #37 Date: July 10, 1990