

0012



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

0271
gh

Norman H. Bangarter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: April 23, 1990
3:30 pm to 4:45 pm

Permittee and/or Operators Name: Soldier Creek Coal Company/Savage Coal Serv.
Business Address: P.O. Box I Price, Utah 84501
Mine Name: Banning Siding Loadout Permit Number: ACT/007/034
Type of Mining Activity: Underground Surface Other loadout fac.
County: Carbon
Company Official (s): none
State Official(s): Rick Summers
Partial: X Complete: _____ Date of Last Inspection: March 7, 1990
Weather Conditions: Cool, recent rain
Acreage: Permitted 36 Disturbed 26.1 Regraded _____ Seeded _____ Bonded 21.4
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	(X)
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/034

DATE OF INSPECTION April 23, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE

c. Sediment Ponds and Impoundments.

The sediment pond was functioning well. A minor amount of runoff water was present in the pond at the time of the inspection. No evidence of recent discharge was evident from precipitation received in the last few days. No quarterly inspection of the pond was required at the time of this inspection.

16. Roads


b. Drainage Controls.

The drainage from the road was adequately controlled with the designed diversions. Vegetation was evident in the diversion. The vegetation appears to be inadequate to control sediment from the area completely. However, silt fencing installed at discharge points was well maintained and no evidence of sediment beyond the fence was observed. The berm around the perimeter of the disturbance was in good repair.

Copy of this Report:

Mailed to: Brian Smith - OSM Dave Spillman - Soldier Creek Coal Co.

Given to: Joe Helfrich and Daron Haddock - DOGM

Inspectors Signature and Number:  #15 Date: 5/1/90