

0014



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: February 14, 1990
8:00am to 9:30am

Permittee and/or Operators Name: Soldier Creek Coal Co./Savage Coal Service
Business Address: P.O. Box I, Price, Utah 84501
Mine Name: Banning Siding Permit Number: ACT/007/034
Type of Mining Activity: Underground Surface Other Loadout
County: Carbon
Company Official (s): Scott Boylen
State Official(s): Lynn Kunzler
Partial: X Complete: Date of Last Inspection: January 30, 1990
Weather Conditions: Partly cloudy and cold
Acreage: Permitted 36 Disturbed 26.1 Regraded Seeded Bonded 21.4
Enforcement Action: None.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	(X)

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/034

DATE OF INSPECTION: Feb. 14, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers: Disturbed area perimeter markers have been installed to include the Substation area that was added as an IBC.

4c. Sediment Ponds and Structures: The sediment pond was inspected and found to be in good condition. A small amount of ice was observed in the bottom of the pond.

4d. Other Sediment Control Measures: Berms around the site were inspected and were in a well maintained condition and appeared to be functioning as designed. The operator was in the process of installing additional silt fence to control runoff from a small borrow area that was used for construction of the substation.

18. Support Facilities and Utility Installations: The operator had recently completed the construction of the substation and was reminded of the commitment to submit 'as-built' drawings.

Copy of this Report:

Mailed to: Brian Smith - OSMRE, Dave Spillman - SCCC, PFO

Given to: Joe Helfrich - DOGM

Inspectors Signature and Number: 

#17 Date: 02/16/90