

0016



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

*SU
JCH*

Norman H. Bangarter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Jan 30, 1990
9:30 a.m. - 11:30 a.m.

Permittee and/or Operators Name: Soldier Creek Coal Co./Savage Coal Service
Business Address: P.O. Box I Price, Utah 84501
Mine Name: Banning Siding Loadout Permit Number: ACT/007/034
Type of Mining Activity: Underground Surface Other Loadout
County: Carbon State: Utah
Company Official(s): Dave Spillman
State Official(s): Daron Haddock
Partial: X Complete: _____ Date of Last Inspection: December 7, 1989
Weather Conditions: Cloudy - Cold
Acreage: Permitted 36.83 Disturbed 26.35 Regraded Seeded Bonded 21.4
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	(X)
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	(X)

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/034

DATE OF INSPECTION Jan. 30, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS:

The operator has identification signs at both points of access to the property. Disturbed area markers are also located around the perimeter of the property.

The operator plans to install additional markers near the new substation where markers should be made more visible.

4c. SEDIMENT PONDS & IMPOUNDMENTS:

The pond has not changed significantly since the last inspection. There is a little ice in the bottom of the pond.

4d. OTHER SEDIMENT CONTROL MEASURES:

Some coal had been spilled in the immediate vicinity of the train loading bin. The operator had the coal quickly cleaned up.

16b. ROAD DRAINAGE CONTROLS:

The silt fences along the roads are up and in good condition.

18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS:

The power substation which has been under construction the last few months, is now essentially complete. A buried cable now supplies electricity to the facility which was previously supplied by a diesel generator. A berm around the pad area directs runoff to the sediment pond and the pad outslope is protected with gravel.

The operator has requested small area exemption status for the outslope. As-built drawings of the substation have been made and should soon be submitted.

Mailed to: Dave Spillman (SCCC)

Mailed to SLC for: John Kathmann (OSM) Joe Helfrich (DOGM)

Filed to: PFO

Daron R. Haddock

Inspectors Signature and Number Daron R. Haddock #28 Date Jan 30, 1990