

0014



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

DEZ
Ad

RECEIVED

MAR 11 1991

**DIVISION OF
OIL GAS & MINING**

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

PERMIT NO.: ACT/007/034
Inspection Date: Feb. 28, 1991

Permittee and/or Operators Name: Soldier Creek Coal Co./Savage
Business Address: P.O. Box I
City: Price State: Utah Zip: 84501
Mine Name: Banning Load Out
County: Carbon State: Utah
Type of Mining Activity: Underground Surface Other
Company Official (s): Johnny Pappas
State Officials (s): Stephen J. Demczak
Time of Inspection: 10:00 (X)a.m. () p.m. to 11:45 (X)a.m. () p.m.
Partial Complete: Date of Last Inspection: Jan. 24, 1991
Weather Conditions: Snowing/Cold/2" Snow
Acreage: Permitted 36 Disturbed Regraded 26.1 Seeded
Bonded 21.4 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. <u>PERMITS</u>	()	()	()	()
2. <u>SIGNS AND MARKERS</u>	()	()	()	()
3. <u>TOPSOIL</u>	()	()	()	()
4. <u>HYDROLOGIC BALANCE:</u>				
a. <u>STREAM CHANNEL DIVERSIONS</u>	()	()	()	()
b. <u>DIVERSIONS</u>	(X)	()	()	(X)
c. <u>SEDIMENT PONDS AND IMPOUNDMENTS</u>	(X)	()	()	(X)
d. <u>OTHER SEDIMENT CONTROL MEASURES</u>	(X)	()	()	(X)
e. <u>SURFACE AND GROUNDWATER MONITORING</u>	()	()	()	()
f. <u>EFFLUENT LIMITATIONS</u>	()	()	()	()
5. <u>EXPLOSIVES</u>	()	()	()	()
6. <u>DISPOSAL OF DEVELOPMENT WASTE AND SPOIL</u>	()	()	()	()
7. <u>COAL PROCESSING WASTE</u>	()	()	()	()
8. <u>NONCOAL WASTE</u>	()	()	()	()
9. <u>PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES</u>	()	()	()	()
10. <u>SLIDES AND OTHER DAMAGE</u>	()	()	()	()
11. <u>CONTEMPORANEOUS RECLAMATION</u>	()	()	()	()
12. <u>BACKFILLING AND GRADING</u>	()	()	()	()
13. <u>REVEGETATION</u>	()	()	()	()
14. <u>SUBSIDENCE CONTROL</u>	()	()	()	()
15. <u>CESSATION OF OPERATIONS</u>	()	()	()	()
16. <u>ROADS</u>				
a. <u>CONSTRUCTION</u>	()	()	()	()
b. <u>DRAINAGE CONTROLS</u>	()	()	()	()
c. <u>SURFACING</u>	()	()	()	()
d. <u>MAINTENANCE</u>	()	()	()	()
17. <u>OTHER TRANSPORTATION FACILITIES</u>	()	()	()	()
18. <u>SUPPORT FACILITIES</u>				
<u>UTILITY INSTALLATIONS</u>	()	()	()	()

INSPECTION REPORT COMMENTS
(continuation sheet)

Page 2 of 2

PERMIT NO. ACT/007/034 INSPECTION DATE February 28, 1991

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE:

b. Diversions:

The diversions at the Banning Loadout facilities were functioning as designed. The diversion ditches contained ice and snow with small amounts of water.

c. Sediment Ponds And Impoundments:

The pond contained a small amount of water, therefore, no discharge was present. The inside slope of the sediment pond showed no signs of erosion and no problems were noted.

d. Other Sediment Control Measures:

Silt fences and straw bales were functional.

Copy of report:

Mailed to: Soldier Creek Coal Co./Savage Coal
Mailed to SLC for: Brian Smith (OSM) Joe Helfrich (DOGM)
Filed to: PFO

Inspectors Signature and Number: Stephen J. Demczak #39
Date: 3/6/91 *Stephen J. Demczak #39*