


# Sunnyside Cogeneration Associates

P.O. Box 10, East Carbon, Utah 84520 • (801) 888-4476 • Fax (801) 888-2538



September 3, 1997

**FAXED**  
9/3/97

*ACT 105105  
FILE FOLDER #215  
AND NOV 97-26-4-1 FILE*

Mr. William J. Malencik  
Division of Oil, Gas and Mining  
c/o College of Eastern Utah  
451 East 400 North  
Price, Utah 84501

RE: Notice of Violation Issued to Sunnyside Cogeneration Associates  
No. N97-26-4-1  
MSHA Identification Numbers

Dear Mr. Malencik:

Attached is a copy of the original letter from the Department of Oil, Gas and Mining that I promised in my letter dated August 28, 1997, to forward upon receipt. It is my understanding this is the final documentation that we will receive from MSHA on the Sunnyside Identification Numbers.

Signs have been ordered for the respective Identification Numbers and they will be posted prior to the September 9, 1997, deadline.

We await your reply on our request to be released from the above referenced Notice of Violation. This has been a long ordeal that we are very anxious to get behind us.

Your cooperation and patience on this matter is appreciated. Please contact me or Rusty Netz with any questions or comments.

Sincerely,  
Sunnyside Cogeneration Associates

Harold C. Sallas  
General Manager

cc: James W. Carter, Utah DOGM	w/attachment
✓ Joe Helfrich, Utah DOGM	w/attachment
Walt Strotz, B&W	w/attachment
John Hill, NRG	w/attachment
Rusty Netz, SOA	w/attachment

U. S. Department of Labor


Mine Safety and Health Administration  
P.O. Box 25367  
Denver, Colorado 80225-0367



AUG 28 1997

Coal Mine Safety and Health  
District 9

Harold C. Sallas  
General Manager  
Sunnyside Cogeneration Associates  
#1 Power Plant Road  
Sunnyside, UT 84539



RE: Sunnyside Waste Coal Site  
Mine ID No. 42-02093  
New Identification Numbers  
Coarse Refuse Pile (Existing)  
East Slurry Cell (Existing)  
West Slurry Cell (Existing)  
Excess Spoils Pile (New)

Dear Mr. Sallas:

In response to your request, dated July 31, 1997, the following three existing structures are being assigned new identification numbers as part of the Sunnyside Cogeneration Associates (SCA) Waste Coal Site:

<u>Structure</u>	<u>Previous Number</u>	<u>New Number</u>
Coarse Refuse Pile	1211-UT-09-01813-02	1211-UT-09-02093-01
East Slurry Cell	1211-UT-09-01813-01	1211-UT-09-02093-02
West Slurry Cell	1211-UT-09-01813-01	1211-UT-09-02093-03

In addition, this letter acknowledges a new refuse pile plan (Excess Spoils Pile), dated August 20, 1997, in accordance with 30 CFR 77.215-2. A review of the Excess Spoils Pile plan indicates that the requirements of 30 CFR 77.214 and 77.215 are incorporated into the proposed plan. The **Excess Spoils Pile** is assigned the following ID number: **1211-UT-09-02093-04**. Identification markers with the new numbers are required for these four structures, according to 30 CFR 77.215-1.

Sincerely,

*John A. Kuzar*  
John A. Kuzar  
District Manager