

0012



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

August 28, 2000

To: Daron Haddock, Permit Supervisor *DRZ*
From: Wm. J. Malencik, Reclamation Specialist *WJM*
Re: Technical Field Visit, Mid-term Review, Sunnyside Cogeneration Associates, Sunnyside Refuse/Slurry, ACT/007/035, Internal File
Other Attendees: Daron Haddock, Joe Helfrich, and Pete Hess
Date & Time: August 22, 2000, 10:00a.m.-2:00p.m.
PURPOSE: Mid-Term Review

OBSERVATIONS/RECOMMENDATIONS/CONCLUSIONS:

Roads

The road going to the rail cut pond is in need of maintenance. It was the DOGM recommendation that water bars be installed and the interior ditch be repaired. This should be done within 30 days.

Water Impoundments

There are eleven water impoundments on the Cogen property. Four are slurry cells and the balance are sediment ponds.

Slurry cells 1 & 2 have been decommissioned and approved to have coal spoil deposited in them as in the approved design. The east slurry cell is not active. The west slurry cell is active and where the current mining is taking place.

The clear water sediment pond is in need of repair. The inlet has eroded. The suggested repair was to install a gradation of angular riprap and grout the inlet with concrete. This needs to be done within 30 days or by September 23, 2000.

sd
cc: Rusty Netz, Sunnyside Cogeneration
O:\007035.SRS\Compliance\2000\fy_082200.wpd