

.0006



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Michael O. Leavitt
Governor
Kathleen Clarke
Executive Director
Lowell P. Braxton
Division Director

1594 West North Temple, Suite 1210
PO Box 145801
Salt Lake City, Utah 84114-5801
801-538-5340
801-359-3940 (Fax)
801-538-7223 (TDD)

February 21, 2001

TO: Internal File
THRU: Daron R. Haddock, Permit Supervisor DRH
FROM: Gregg A. Galecki, Reclamation Specialist GA
RE: 2000 Second Quarter Water Monitoring, Sunnyside Cogeneration Assoc., Sunnyside Refuse/Slurry, 035-WQ00-2

1. Were data submitted for all of the MRP required sites? YES [x] NO []
Identify sites not monitored and reason why, if known:

2. On what date does the MRP require a five-year resampling of baseline water data.
See Technical Directive 004 for baseline resampling requirements. Consider the five-year baseline resubmittal when responding to question one above. Indicate if the MRP does not have such a requirement.

Resampling Due Date

During the year preceding each re-permitting action: "Once every five years (prior to each application for permit renewal) one sample from each of the monitoring sites listed in Table 7-2A will be sampled and analyzed for the parameters listed in Table 7-2B". The current permit term expires **February 4, 2003.**

3. Were all required parameters reported for each site? YES [] NO [x]
Comments, including identity of monitoring site:
Oil & Grease and TDS were absent from sample Well-1.

4. Were irregularities found in the data? YES [] NO [x]
Comments, including identity of monitoring site:

5. Were DMR forms submitted for all required sites?

1st month, YES [x] NO []
2nd month, YES [x] NO []
3rd month, YES [x] NO []

Identify sites and months not monitored:

No Discharge was reported at all sites.

6. Were all required DMR parameters reported?

YES [x] NO []

Comments, including identity of monitoring site:

No Discharge was reported.

7. Were irregularities found in the DMR data?

YES [] NO [x]

Comments, including identity of monitoring site:

No Discharge was reported at all sites.

8. Based on your review, what further actions, if any, do you recommend?

No further action is necessary. The operator will be contacted to confirm the status of the O/G and TDS analysis for Well-1.