



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

October 8, 2015

Gerald Hascall, Plant Manager
Sunnyside Cogeneration Associates
One Power Plant Road
P. O. Box 159
Sunnyside, Utah 84539

Subject: Culverts & Roads, Sunnyside Cogeneration Associates, Sunnyside Refuse, C/007/0035, Task ID #4963

Dear Mr. Hascall:

The Division has reviewed your application. The Division has identified deficiencies that must be addressed before final approval can be granted. The deficiencies are listed as an attachment to this letter.

The deficiencies authors are identified so that your staff can communicate directly with that individual should questions arise. The plans as submitted are denied. Please resubmit the entire application.

If you have any questions, please call me at (801) 538-5325.

Sincerely,

Daron R. Haddock
Coal Program Manager

DRH/sqs

O:\007035.SRS\WG4963 CULVERTS & ROADS\Deficiencies.doc



GARY R. HERBERT
Governor
GREG BELL
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
MICHAEL R. STYLER
Executive Director
Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Technical Analysis and Findings

Utah Coal Regulatory Program

PID: C0070035
TaskID: 4963
Mine Name: SUNNYSIDE REFUSE & SLURRY
Title: CULVERTS AND ROADS

Operation Plan

Road System Plans and Drawings

Deficiencies Details:

The application does not meet the minimum requirements of R645-301-521.170 by submitting plans and drawing for each road, conveyor, and rail system to be used within the proposed permit area. The application does not meet the minimum requirements of R645-301-534.100 due to missing updated information within the MRP Chapter 5 Section 527.

The application included all the required plans and drawing for each road to be maintained within the permit area relevant to the upcoming ash disposal area as detailed in 5-2K; however, the text within Chapter 5 Section 527 (page 500-13) was not updated to include Plate 5-2K for the typical cross-sections of the road and plans. Appendix 5-7 details the road descriptions and was not updated within the application to include the new primary use of the road.

The Permittee will:

1. Update the text within Chapter 5 Section 527 to include 5-2K as a cited drawing for more information.
2. Update Appendix 5-7 to include a description of the new use and characteristics of Road S and Road T and drawing 5-2K, along with any other relevant road details that need to be updated.

cparker

Hydrologic Impoundments

Deficiencies Details:

R645-301-742 The current MRP does not contain any information on a ""Pond 018"" as listed on revised page 700-6. Any reference to this pond should be removed.

R645-301-742 Sheet 7-18 should be updated to reflect changes to ditch D-9 and to the pond inlets.

adaniels