

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/038 DATE OF INSPECTION: May 10, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

The permit will expire on July 9, 1993 and the reclamation should take place prior to expiration. The permanent seed mix may take place in the fall with consultation from the biologist.

3. Topsoil -

The inspection reveals that self-induced vegetative cover has started to grow on the topsoil pile at the fansite. All piles, at this time, show no signs of erosion.

4c. Other Sediment Control Measures -

Catch basins were stable and did not contain any water.

14. Subsistence Control -

The gate and part of the road to the old Castle Gate mine has subsided due to old underground working in the 1960's. The exploration program has not contributed to the subsidence. The operator will backfill the subsidence at the gate and access road. It would not be prudent to take heavy equipment across the subsidence, until the road is fixed and inspected by operator.

21. Bonding and Insurance -

The bond for the exploration permit is for the amount of \$50,000.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Cyprus Plateau Mining/Western Coal Company


Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: May 12, 1993

Inspector's Signature and Number:


Stephen J. Demczak

#39