



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

## INSPECTION REPORT

*John [unclear]*

Norman H. Bangarter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

Partial: \_\_\_\_\_ Complete: \_\_\_\_\_ Exploration XX  
Inspection Date/Time: March 16, 1993/01:00pm-02:00pm  
Date of Last Inspection: February 6, 1993

Mine Name: Blackhawk Site County: Carbon Permit Number: ACT/007/038  
Permittee and/or Operator's Name: Cyprus Plateau Mining/Western Coal Company  
Business Address: P. O. Box PMC, Price, UT 84501  
Type of Mining Activity: Underground Surface \_\_\_\_\_ Prep. Plant \_\_\_\_\_ Other XX  
Officials(s): State: Stephen J. Demczak Company: \_\_\_\_\_  
Federal Official(s): \_\_\_\_\_ Weather Conditions: 40's clear  
Existing Acreage: Permitted-11,500 Disturbed-3.7 Regraded-Seeded-0 Bonded-3.7  
Increased/Decreased: Permitted-\_\_\_\_\_ Disturbed-\_\_\_\_\_ Regraded-\_\_\_\_\_ Seeded-\_\_\_\_\_ Bonded-\_\_\_\_\_  
Status: X Exploration/\_\_\_\_\_ Active/\_\_\_\_\_ Inactive/\_\_\_\_\_ Temp Cessation/\_\_\_\_\_ Bond Forfeiture  
Reclamation ( Phase I/Phase II/Final Bond Release/Liability \_\_\_\_\_ Year)

### REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

#### Instructions

- Substantiate the elements on this inspection by checking the appropriate performance standard.
  - For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
  - For partial inspections check only the elements evaluated.
- Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

	EVALUATED	N/A	COMMENTS	NOV/ENF
1. PERMITS, CHANGE, TRANSFER, RENEWAL, SALE	[ ]	[ ]	[ ]	[ ]
2. SIGNS AND MARKERS	[ ]	[ ]	[ ]	[ ]
3. TOPSOIL	[XX]	[ ]	[ ]	[ ]
4. HYDROLOGIC BALANCE:				
a. DIVERSIONS	[XX]	[ ]	[XX]	[ ]
b. SEDIMENT PONDS AND IMPOUNDMENTS	[ ]	[ ]	[ ]	[ ]
c. OTHER SEDIMENT CONTROL MEASURES	[XX]	[ ]	[ ]	[ ]
d. WATER MONITORING	[ ]	[ ]	[ ]	[ ]
e. EFFLUENT LIMITATIONS	[ ]	[ ]	[ ]	[ ]
5. EXPLOSIVES	[ ]	[ ]	[ ]	[ ]
6. DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	[ ]	[ ]	[ ]	[ ]
7. COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	[XX]	[ ]	[XX]	[ ]
8. NONCOAL WASTE	[ ]	[ ]	[ ]	[ ]
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	[ ]	[ ]	[ ]	[ ]
10. SLIDES AND OTHER DAMAGE	[ ]	[ ]	[ ]	[ ]
11. CONTEMPORANEOUS RECLAMATION	[ ]	[ ]	[ ]	[ ]
12. BACKFILLING AND GRADING	[ ]	[ ]	[ ]	[ ]
13. REVEGETATION	[ ]	[ ]	[ ]	[ ]
14. SUBSIDENCE CONTROL	[ ]	[ ]	[ ]	[ ]
15. CESSATION OF OPERATIONS	[ ]	[ ]	[ ]	[ ]
16. ROADS:				
a. CONSTRUCTION/MAINTENANCE/SURFACING	[ ]	[ ]	[ ]	[ ]
b. DRAINAGE CONTROLS	[ ]	[ ]	[ ]	[ ]
17. OTHER TRANSPORTATION FACILITIES	[ ]	[ ]	[ ]	[ ]
18. SUPPORT FACILITIES/UTILITY INSTALLATIONS	[ ]	[ ]	[ ]	[ ]
19. AVS CHECK (4th Quarter-April, May, June)	[ ]	[ ]	[ ]	[ ]
20. AIR QUALITY PERMIT	[ ]	[ ]	[ ]	[ ]
21. BONDING & INSURANCE	[ ]	[ ]	[ ]	[ ]

INSPECTION REPORT  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/038 DATE OF INSPECTION: March 16, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

4a. Diversions -

The diversions at the fan site were uncovered from snow. The diversions were functioning but could use some spring maintenance and check for proper sizing. The other locations were still snow covered but would likely need maintenance after the snow melts.

4c. Other Sediment Control Measures -

The silt fences located at the fan site have considerable deposition of material in front of the silt structure. Spring cleaning should be performed to ensure peak performance on these structures.

7. Coal Mine Waste -

Several piles of mine waste have been placed at the temporary mine waste site. The mine waste is draining to a catch basin.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Cyprus Plateau Mining/Western Coal Company

Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: March 22, 1993

Inspector's Signature and Number: Stephen J. Demczak

  
Stephen J. Demczak

#39