

May 23, 2003

TO: Internal File  
THRU: Daron R. Haddock, Permit Supervisor  
FROM: Dana Dean, P.E./Senior Reclamation Hydrologist  
RE: 2002 Fourth Quarter Water Monitoring, Plateau Mining Corporation, Willow Creek Mine, C/007/038-WQ02-4

- 1. Was data submitted for all of the MRP required sites?** YES  NO   
*Identify sites not monitored and reason why, if known:*

No Access was reported at site B-51. The road to the site was severely rutted, preventing a vehicle from passing.

- 2. On what date does the MRP require a five-year resampling of baseline water data.**  
See Technical Directive 004 for baseline resampling requirements. Consider the five-year baseline resubmittal when responding to question one above. Indicate if the MRP does not have such a requirement.

**Resampling due date** The Willow Creek Mine is in reclamation and does not have any resampling of baseline water data scheduled.

- 3. Were all required parameters reported for each site?** YES  NO   
*Comments, including identity of monitoring site:*

- 4. Were irregularities found in the data?** YES  NO   
*Comments, including identity of monitoring site:*

**5. Were DMR forms submitted for all required sites?**

1 <sup>st</sup> month,	YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>
2 <sup>nd</sup> month,	YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>
3 <sup>rd</sup> month,	YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>

**6. Were all required DMR parameters reported?**

YES  NO

*Comments, including identity of monitoring site:*

**7. Were irregularities found in the DMR data?**

YES  NO

*Comments, including identity of monitoring site:*

**8. Based on your review, what further actions, if any, do you recommend?**

No Further actions are necessary.