

July 30, 2003

TO: Internal File

THRU: Daron R. Haddock, Permit Supervisor

FROM: Dana Dean, P.E., Senior Reclamation Hydrologist

RE: 2003 Second Quarter Water Monitoring, Plateau Mining Corporation, Willow Creek Mine, C/007/0038-WQ03-2, Task ID #1622

- 1. Was data submitted for all of the MRP required sites?** YES  NO   
*Identify sites not monitored and reason why, if known:*

- 2. On what date does the MRP require a five-year resampling of baseline water data.**  
See Technical Directive 004 for baseline resampling requirements. Consider the five-year baseline resubmittal when responding to question one above. Indicate if the MRP does not have such a requirement.

**Resampling due date**

The Willow Creek Mine is in reclamation and does not have any baseline resampling scheduled.

- 3. Were all required parameters reported for each site?** YES  NO   
*Comments, including identity of monitoring site:*

The Permittee reported "no-flow" at sites B-25 and B-26. They reported all required parameters for the remaining sites.

- 4. Were irregularities found in the data?** YES  NO   
*Comments, including identity of monitoring site:*

Site B151 had a reported total alkalinity of 502 mg/l, which is 2.31 standard deviations greater than the average of 303.15.

**5. Were DMR forms submitted for all required sites?**

1 <sup>st</sup> month,	YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>
2 <sup>nd</sup> month,	YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>
3 <sup>rd</sup> month,	YES <input checked="" type="checkbox"/>	NO <input type="checkbox"/>

**6. Were all required DMR parameters reported?**

YES  NO

*Comments, including identity of monitoring site:*

All DMRs reported "no-flow."

**7. Were irregularities found in the DMR data?**

YES  NO

*Comments, including identity of monitoring site:*

All DMRs reported "no-flow."

**8. Based on your review, what further actions, if any, do you recommend?**

No further actions are necessary at this time.