

0060

Incoming ok
0070039
Task 2580

From: "Miller, Vicky" <VMiller@archcoal.com>
To: "Pete Hess" <petehess@utah.gov>, "Pam Grubaugh-Littig" <PAMGRUBAUGHLITTIG@utah.gov>, "Wayne Hedberg" <WAYNEHEDBERG@utah.gov>
Date: 7/27/2006 2:38:24 PM
Subject: RE: G-13 through G-17

Pete, Pam, Wayne, Jerriann, Priscilla, Steve, Wayne and Sheila,

First of all I apologize for the trouble this will cause most of you, but due to faulting we need to change our mine plan. We thought we were ahead of the game with well pad construction and drilling of Degas Wells, however our original assumptions were incorrect. We will complete drilling our prepared sites by August 12th and will need to be ready to construct well sites for G-14 and G-13 at that time.

We believe we have addressed the outstanding deficiencies for wells G-13, G-14, and G-15 thru G-17, but realize you will need to review the submittal associated with the deficiencies. Please let me know if I can be of any assistance.

As you may or may not be aware, drillers are few and far between and if we release the drillers to go to another location/company because of a permitting delay, we will not get them back this year. The wells not only assist with health and safety issues, they are being required by MSHA.

Nothing like being caught between a rock and a hard place. I am open to a meeting if you believe that will help with the review and subsequent approval. Thank you for your time and consideration. Vicky Miller

-----Original Message-----

From: Pete Hess [mailto:petehess@utah.gov]
Sent: Wednesday, July 26, 2006 10:00 AM
To: Pam Grubaugh-Littig; Wayne Hedberg
Cc: Jerriann Ernstsens; Priscilla Burton; Sheila Morrison; Steve Christensen; Wayne Western
Subject: G-13 through G-17

As of 7:26 AM this morning, the Permittee is requesting that we proceed with reviewing the Task ID #2580 response such that we might be able to grant approval for at least G-13 by mid-August. I am not sure who had deficiencies relative to the last round of deficiencies. The need for this is due to faulting in the current panel, and a need for a change to the mine plan.

If you had deficiencies for the Task ID # 2456 response, please work of the 2580 submittal such that the Permittee can get going on G-13 in a timely manner.

I know we are all incredibly busy. Thank you.

***** Email Disclaimer *****

The information contained in this e-mail, and in any accompanying documents, may constitute confidential and/or legally privileged information. The information is intended only for use by the designated recipient. If you are not the intended

recipient (or responsible for delivery of the message to the intended recipient), you are hereby notified that any dissemination, distribution, copying, or other use of, or taking of any action in reliance on this e-mail is strictly prohibited. If you have received this e-mail communication in error, please notify the sender immediately and delete the message from your system.

CC: "Jerriann Ernstsén" <JERRIANNERNSTSEN@utah.gov>, "Priscilla Burton" <PRISCILLABURTON@utah.gov>, "Sheila Morrison" <SHEILAMORRISON@utah.gov>, "Steve Christensen" <STEVECHRISTENSEN@utah.gov>, "Wayne Western" <WAYNEWESTERN@utah.gov>